



EAGLE
Environmental, Inc.

- Industrial Hygiene / IAQ
- Hazardous Building Materials
- Environmental Assessments
- Laboratory Services & Training

July 26, 2018

Mr. Ronald Turner
Director of Operations
Town of East Haddam
26 Plains Road
P.O. Box 401
Moodus, Connecticut 06469

**RE: Pre-Renovation/Demolition Hazardous Building Materials Inspection Report
Former River House
1 Main Street
East Haddam, Connecticut
Eagle Project No. 18-144.10T3**


Dear Mr. Turner:

Please find the report for the hazardous building materials inspection conducted at the Former River House Building located at 1 Main Street in East Haddam, Connecticut. The scope of services included an asbestos-containing materials inspection, lead-based paint screen, a visual inspection for polychlorinated biphenyls (PCB) and an inspection for universal waste materials.


The inspection was performed to support the potential renovation or demolition of the building.

Please do not hesitate to contact us if you have any questions regarding the contents of this report.

Sincerely,
Eagle Environmental, Inc.



Report Prepared By:
Chris Liberti
Senior Project Manager



Report Reviewed By:
Ashis Roychowdhury
Executive Vice President

\\Eaglesvr\public\2018 Files\2018 Reports\East Haddam, Town of\River House\1 Main St - Haz Inspection Report.doc

TABLE OF CONTENTS

| | |
|---|----------|
| 1. INTRODUCTION | 1 |
| 1.1 BUILDING DESCRIPTION..... | 1 |
| 2. SCOPE OF INSPECTION | 1 |
| 2.1 ASBESTOS CONTAINING MATERIALS | 1 |
| 2.2 LEAD-BASED PAINT | 1 |
| 2.2.1 X-Ray Fluorescence Screen..... | 1 |
| 2.2.2 Lead Waste Characterization | 2 |
| 2.3 POLYCHLORINATED BIPHENYLS (PCB) IN BULK SOURCE MATERIALS | 2 |
| 2.4 UNIVERSAL WASTE MATERIALS AND OTHER ENVIRONMENTAL CONCERNS | 2 |
| 2.4.1 Polychlorinated Biphenyls (PCB) and Di-ethylhexylphthalate (DEHP) Containing Items..... | 2 |
| 2.4.2 Mercury Containing Items | 3 |
| 2.4.3 Used Electronics and Batteries | 3 |
| 2.4.4 Chlorofluorocarbons | 3 |
| 3. INSPECTION PROTOCOLS | 3 |
| 3.1 ASBESTOS CONTAINING MATERIALS | 3 |
| 3.1.1 Inspection..... | 3 |
| 3.1.2 Bulk Sampling | 4 |
| 3.1.3 Bulk Sample Analysis..... | 4 |
| 3.2 LEAD-BASED PAINT | 5 |
| 3.2.1 X-Ray Fluorescence Screen..... | 5 |
| 3.2.2 Lead Waste Characterization | 6 |
| 3.3 POLYCHLORINATED BIPHENYLS (PCB) IN BULK SOURCE MATERIALS | 7 |
| 3.3.1 Visual Inspection | 7 |
| <p>EAGLE PERFORMED A VISUAL INSPECTION ONLY OF SUSPECT PCB CONTAINING MATERIALS AT THE BUILDING. AN INVENTORY OF SUSPECT PCB-CONTAINING MATERIALS WAS DEVELOPED FOR THE BUILDING. THESE MATERIALS WERE ASSUMED TO CONTAIN PCB'S IN CONCENTRATIONS EXCEEDING 50 PARTS PER MILLION (PPM). MATERIALS ASSUMED TO CONTAIN PCB'S THAT WILL BE IMPACTED BY THE RENOVATION OR DEMOLITION ACTIVITIES MUST BE TREATED AS A BULK PRODUCT WASTE AND PROPERLY DISPOSED OF IF IMPACTED DURING CONSTRUCTION ACTIVITIES UNLESS SAMPLES ARE COLLECTED TO ASCERTAIN THE ACTUAL CONCENTRATIONS.</p> | |
| 3.4 UNIVERSAL WASTE MATERIALS AND OTHER ENVIRONMENTAL CONCERNS | 7 |
| 3.4.1 PCB and Di-ethylhexylphthalate (DEHP) Containing Items..... | 7 |
| 3.4.2 Mercury Containing Items | 7 |
| 3.4.3 Used Electronics and Batteries | 7 |
| 3.4.4 Chlorofluorocarbons | 7 |
| 4. INSPECTION RESULTS | 8 |
| 4.1 ASBESTOS CONTAINING MATERIALS | 8 |
| 4.2 LEAD-BASED PAINT | 9 |

| | | |
|-----------|--|-----------|
| 4.2.1 | X-Ray Fluorescence Screen | 9 |
| 4.2.2 | Lead Waste Characterization Results | 10 |
| 4.3 | PCB INSPECTION RESULTS SUMMARY | 10 |
| 4.4 | UNIVERSAL WASTE MATERIALS AND OTHER ENVIRONMENTAL CONCERNS | 10 |
| 4.4.1 | PCB and Di-ethylhexlpthalate (DEHP) Containing Items..... | 10 |
| 4.4.2 | Mercury Containing Items | 11 |
| 4.4.3 | Used Electronics and Batteries | 11 |
| 4.4.4 | Chlorofluorocarbons | 11 |
| 5. | COST ESTIMATES | 11 |

LIST OF TABLES

| | |
|-----------|---|
| Table I | Asbestos-Containing Materials Summary Table |
| Table II | Non Asbestos-Containing Materials Summary Table |
| Table III | Universal Waste Materials Summary Table |

APPENDICES

| | |
|------------|---|
| Appendix 1 | Floor Plans and Roof Plans with Sample Location Diagrams |
| Appendix 2 | Asbestos Bulk Sample Laboratory Reports |
| Appendix 3 | XRF Lead-based Paint Inspection Reports |
| Appendix 4 | Abatement and Consulting Cost Estimates |
| Appendix 5 | Eagle Environmental Inc. Licenses and Laboratory Certificates |

1. INTRODUCTION

On June 20, 2018, Eagle Environmental, Inc. (Eagle) conducted a hazardous building material inspection of the Former River House located at 1 Main Street in East Haddam, Connecticut. The scope of the hazardous building material inspection included an asbestos-containing materials inspection, a lead-based paint screen, a visual inspection for suspect PCB-containing materials and an inspection for universal waste materials. The inspection was performed to support the potential renovation or demolition of the building.

1.1 Building Description

One of the two subject buildings located at 1 Main Street in East Haddam, Connecticut is a two-story residential structure of wood frame construction known as the River House. The structure was built in 1930 and appeared to have undergone minor renovations over time. The building is constructed over a full basement. The existing mechanical equipment consists of an oil-fired boiler with cast iron radiators. Remnants of an abandoned forced hot air duct system remain in the plaster walls. The existing steam distribution system is un-insulated. The basement piping is exposed and all risers are contained within the walls on the floors above. The abandoned duct system is insulated with asbestos-containing (AC) paper. The boiler is located in the basement of the structure. The interior walls and ceilings are of a two-coat plaster on gypsum backer board system. The kitchen has been renovated and contains a small amount of sheetrock and joint compound on the walls. The window frames and sashes are of wood construction. The door frames are wood with wood doors. The floors are hardwood and the kitchen and bathroom are finished with resilient flooring finishes. The exterior facades are clad with wood clapboard siding on the first floor and wood shakes on the second floor. The main roof is pitched with a sloped porch roof. The roof is covered with wood shakes and two layers of asphalt shingles.

2. SCOPE OF INSPECTION

2.1 Asbestos Containing Materials

The asbestos inspection was conducted in order to satisfy the United States Environmental Protection Agency (USEPA) National Emission Standard for Hazardous Air Pollutants Act (NESHAP) as amended November 20, 1990. The USEPA NESHAP final rule requires the identification and removal of all regulated ACM in a building prior to demolition or in an area of renovation prior to renovating the area if the renovation work will impact the ACM.

The asbestos inspection was performed by Raymond R. Folino; a State of Connecticut licensed Asbestos Inspector (license #000137).

2.2 Lead-based Paint

2.2.1 X-Ray Fluorescence Screen

The lead-based paint (LBP) screen was performed in accordance with the requirements of the State of Connecticut, Department of Energy and Environmental Protection (DEEP), Guidance for the Management and Disposal of Lead Contaminated Materials Generated in the Lead Abatement, Renovation and Demolition Industries. The DEEP regulates the disposal of hazardous lead waste in the State of Connecticut. Lead-contaminated debris, not contaminated with

other hazardous materials, is classified either as hazardous lead waste or as non-hazardous solid waste.

Additionally, the U.S. Department of Labor Occupational Safety and Health Administration (OSHA) regulates lead dust exposure to workers in the construction industry under 29 CFR 1926.62 Lead in Construction.

The lead-based paint screen was performed by Alexis St. Hilaire a State of Connecticut licensed Lead Inspector/Risk Assessor (license #002282).

2.2.2 Lead Waste Characterization

The DEEP regulates the disposal of hazardous waste. The required analytical test to determine a materials waste classification is the Toxicity Characteristic Leachate Procedure, or TCLP (Regulation of State DEEP 22a-449© - 101 (a) (1), incorporating 40 CFR 262.24). Eagle reviewed the XRF data for the building but did not collect TCLP samples of building materials for lead waste characterization at this time, as the extent of renovations was unknown.

2.3 Polychlorinated Biphenyls (PCB) in Bulk Source Materials

Eagle performed a visual inspection only of suspect PCB containing materials at the site building. These materials included paints, caulks, glazing compounds, adhesives and other sealants/coatings. PCBs have been identified by the USEPA as a concern in caulk and glazing compounds. The USEPA has identified numerous cases where PCBs have been added to these and other materials between 1930 and 1979 to improve adhesion and flexibility.

The USEPA regulates the removal and disposal of PCB-containing materials if the concentration of PCB's are found to contain equal to or greater than fifty (50) parts-per-million (ppm). The USEPA also regulates soil and adjacent substrate materials contaminated by PCB-containing materials containing greater than or equal to fifty (50) ppm if the soil or substrates contain greater than one (1) ppm PCB.

The DEEP regulates the removal and disposal of source materials, soil, or substrate materials with PCB concentrations in excess of one (1) ppm. Materials with PCB concentrations less than one (1) ppm are not regulated by USEPA or DEEP and their unrestricted use or disposal with regard to PCB is not subject to State or Federal Regulation.

2.4 Universal Waste Materials and Other Environmental Concerns

2.4.1 Polychlorinated Biphenyls (PCB) and Di-ethylhexlpthalate (DEHP) Containing Items

PCB and DEHP lighting ballasts and electrical equipment, including capacitors and switches that contain PCBs, are regulated under the Toxic Substances Control Act of 1976 (TSCA) which bans the manufacturing and distribution of PCBs and regulates their storage and disposal.

PCBs and DEHP can be found in a number of items, including lighting ballast and electrical equipment, including capacitors and switches. DEHP and PCB-containing items such as these must be managed and disposed of in accordance

with special requirements. A visual inspection for PCB and DEHP containing items was performed at the site building.

2.4.2 Mercury Containing Items

Fluorescent lamps, thermostats, mercury switches, manometers, natural gas meters and other items can contain enough mercury to be classified as a special waste, and therefore may not be disposed of as regular construction debris. The mercury and mercury vapors associated with these products must be reclaimed prior to disposal or recycling of the products. A visual inspection for the presence of fluorescent lamps, thermostats and switches potentially containing mercury was performed at the site building.

2.4.3 Used Electronics and Batteries

Used electronics and batteries may contain enough lead, mercury, cadmium or acid electrolytes to be classified as universal waste. In such cases, they may not be disposed of as regular construction debris. A visual inspection for the presence of used electronic devices was performed at the site building.

2.4.4 Chlorofluorocarbons

Freon gas includes a number of gaseous, colorless chlorofluorocarbons (CFCs) that are commonly used as refrigerants. Freon is listed as a controlled substance by governments around the world. In the United States, the USEPA regulates the emission of Freon gas into the atmosphere due to its ozone depleting capabilities. Through Title VI, Stratospheric Ozone Protection, of the Clean Air Act Amendments of 1990, the USEPA regulates Freon gas and requires mandatory recycling and a ban on the intentional venting or releasing of refrigerants during maintenance, service and or repair. A visual inspection for the presence of building materials potentially containing Freon was performed at the site building.

3. INSPECTION PROTOCOLS

3.1 Asbestos Containing Materials

3.1.1 Inspection

The asbestos-containing materials (ACM) inspection included the accessible interior and exterior portions of the building including the roofing systems. Semi-destructive testing techniques were utilized during the inspection process. This included cutting through various layers of flooring and roofing materials to verify and sample individual layers of suspect ACM. Suspect building materials that are inaccessible for inspection and sampling are assumed to be ACM for the purpose of this report. These suspect materials are generally located in operational equipment, behind rigid walls and ceilings, below rubber roof membranes or otherwise concealed areas of the building, including below grade materials.

During the inspection, suspect materials are located, sampled, quantified and the friability of the material is determined. Friable materials are those materials that hand pressure can crumble, pulverize or reduce to powder when dry. An estimated quantity of identified ACM is provided for positive materials only. The materials are quantified in linear or square feet, depending on the nature of the material.

3.1.2 Bulk Sampling

During the sampling process, suspect ACM is separated into three (3) USEPA categories. These categories are: Thermal System Insulation (TSI), Surfacing Materials (SURF), and Miscellaneous materials (MISC). TSI includes all materials used to prevent heat loss or gain or water condensation on mechanical systems. Examples of TSI are pipe covering, boiler insulation, duct wrap, and mudpack fitting cement. Surfacing ACM includes all ACM that is sprayed, troweled or otherwise applied to an existing surface. These applications are most commonly used in fireproofing, decorative, and acoustical applications. Miscellaneous materials include all ACM not listed in thermal or surfacing, such as linoleum, vinyl asbestos flooring, and ceiling tile.

Bulk sampling was performed in a random method. Bulk sampling methods and number of samples collected meets or exceeds the USEPA requirements.

3.1.3 Bulk Sample Analysis

The samples of the suspect asbestos containing materials were sent to a State of Connecticut Department of Public Health (DPH) approved laboratory for analysis by Polarized Light Microscopy (PLM). PLM is the USEPA accepted method of analysis for identification of asbestos in bulk matrices. Samples are collected individually or in sets. When sets of samples are collected, each set is systematically analyzed until one sample is determined to contain asbestos. Upon the determination of the presence of asbestos in one sample in the set, analysis of the remaining samples in the set is discontinued. If no asbestos is observed during analysis of the set of samples, the suspect material is determined to be negative for asbestos content.

Sample analysis results are reported in percentage of asbestos and non-asbestos components. The USEPA defines any material that contains greater than one percent asbestos, utilizing PLM, as being an asbestos-containing material (ACM). Suspect materials containing greater than one percent (1%) asbestos utilizing the PLM Point Count Method and the NOB TEM method are also considered to be asbestos-containing. Materials determined to contain greater than one percent (1%) asbestos is regulated by the USEPA, the State of Connecticut Department of Public Health and Department of Energy and Environmental Protection and the United States Department of Labor. Sample results indicating "no asbestos detected" (NAD) are specified as non-asbestos containing materials. Samples results indicating "Did Not Analyze" (DNA) are not analyzed due to the stop on first positive request to the laboratory.

3.1.3.1 Friable ACM Analysis

Certain samples of friable materials shown to contain less than 10% asbestos are analyzed further by the "Point Count Method". This procedure is recommended by the United States Environmental Protection Agency to confirm friable bulk samples shown to have less than 10% asbestos by PLM to be definitively negative or positive for asbestos. This method is accepted as providing statistically reliable results when analyzing bulk samples with very low asbestos concentrations. Friable materials containing "Trace" or "less than one percent (1%)" asbestos must be analyzed by the PLM Point Count Method. None of the samples were further analyzed by the PLM Point Count Method for this project.

3.1.3.2 Non Friable ACM Analysis

Certain samples of organically bound non-friable materials shown to contain "less than 1% asbestos", "TRACE" or "NAD" are recommended for analyses by the "NOB TEM ELAP 198.4 Method". This procedure is recommended by the United States Environmental Protection Agency to further evaluate non-friable organically bound materials for asbestos. Suspect materials confirmed by NOB TEM to be "less than 1% asbestos", "TRACE" or "NAD" are considered non-asbestos containing. None of the samples were further analyzed by the NOB TEM Method for this project.

3.2 Lead-based Paint

3.2.1 X-Ray Fluorescence Screen

The lead-based paint screen was performed utilizing an X-Ray Fluorescence (XRF) Radiation Monitoring Device (RMD) Lead Paint Analyzer (LPA 1), serial number 3611 within the limits of the inspection area(s). The screen includes only accessible areas within the inspection area(s) and accessible building materials.

The lead-based paint screen includes testing limited components and or surfaces throughout the structure. It is not the intent to test all painted components, but to identify on a broad scale the impact of lead paint as it relates to the disposal of lead paint contaminated debris and potential worker exposure issues. Generally, wall and ceiling surfaces, painted floors, window and door systems are tested. Other components such as baseboards, cabinets, columns, trim, etc. are tested on a limited basis. Component and surface locations are identified by side designations represented by the letters "A", "B", "C", and "D". The "A" side is considered the front of the building with the "B", "C", and "D" sides following in a clockwise order.

The data is presented on computer generated Lead Inspection Reports contained in Appendix 3. The Summary Report provides an inventory of each surface coating that contains lead at or above 1.0 mg/cm². The Detailed Report is an inventory of each tested surface on a room-by-room basis.

For the purpose of this report, the XRF results are separated into two (2) categories; high levels of lead (≥ 1.0 mg/cm²) and low levels of lead (<1.0 mg/cm²). Building materials containing high levels of lead have a greater probability of creating worker exposures during construction than do building materials with low levels of lead. Additionally, lead waste characterization sampling is required for building materials containing high levels of lead (≥ 1.0 mg/cm²) and will become a waste product as a result of demolition or renovation activities.

The U.S. Department of Labor Occupation Safety and Health Administration (OSHA) regulates lead dust exposure to workers in the construction industry under 29 CFR 1926.62 Lead Exposure in Construction; Interim Final Rule. Currently, OSHA does not define a threshold level of lead in paint that may cause worker exposure. Any detectable level of lead in paint (>0.0 mg/cm² +/- 0.3 mg/cm² by XRF or ≥ 0.01 % by AAS) requires task specific exposure monitoring.

3.2.2 Lead Waste Characterization

The DEEP regulates the disposal of hazardous waste. The required analytical test to determine a materials waste classification is the Toxicity Characteristic Leachate Procedure, or TCLP (Regulation of State DEEP 22a-449© - 101 (a) (1), incorporating 40 CFR 262.24).

The TCLP test subjects a 100-gram sample of waste material to a simulated landfill leaching condition, and assesses the ability of the sample to leach out lead into the environment. The waste is classified as hazardous lead waste if the TCLP sample result is greater than 5.0 mg/l of lead. The waste is classified as non-hazardous solid waste if the TCLP sample result is less than 5.0 mg/l of lead. Building debris containing equal to or greater than 1.0 mg/cm² of lead by XRF requires waste classification analysis.

There are two (2) primary approaches for TCLP sampling. Both methods utilize the data generated during the lead screen to determine which building materials contain lead in paint coatings and what percentage of the waste stream will consist of the leaded materials. The two (2) basic approaches are described below.

Screen, Sample, and Segregate Method

The Screen, Sample, and Segregate method of TCLP sampling is conducted in accordance with the State of Connecticut Department of Energy and Environmental Protection Guidance for the Management and Disposal of Lead-Contaminated Materials Generated in the Lead Abatement, Renovation, and Demolition Industries. This method entails screening the building components scheduled to be removed with an XRF lead paint analyzer. Components that are determined to be lead containing are sampled and analyzed by TCLP based on their contribution into the waste stream. The waste stream is made up of those building components that will be removed from the structure as part of the renovation or demolition process and will become a waste product.

Sample and Demolish Method

The Composite Sample and Demolish Method of TCLP sampling is conducted in accordance with the State of Connecticut Department of Energy and Environmental Protection Guidance for the Management and Disposal of Lead-Contaminated Materials Generated in the Lead Abatement, Renovation, and Demolition Industries. This method utilizes composite samples to assess the total amount of leachable lead of the entire quantity of debris to be removed. This sampling method is best utilized for whole building demolitions where the quantity of non-lead debris is expected to be much greater than that of the leaded debris. The first step in the sampling process requires the inspector to identify the potential waste stream of the structure to be demolished. The waste stream is made up of those building components that will be disposed of once the structure is demolished. The inspector calculates the mass by weight of each group of building components within the building (i.e. studs, framing, sheathing, siding, doors, windows, etc.). The lead testing results enables the inspector to determine the percentages of components, within each group, that contain lead. With this information, the inspector can then calculate the percent by weight contribution of each components contribution into the waste stream. This takes into account the ratio of leaded components verse non-leaded components within each group.

3.3 Polychlorinated Biphenyls (PCB) in Bulk Source Materials

3.3.1 Visual Inspection

Eagle performed a visual inspection only of suspect PCB containing materials at the building. An inventory of suspect PCB-containing materials was developed for the building. These materials were assumed to contain PCB's in concentrations exceeding 50 parts per million (ppm). Materials assumed to contain PCB's that will be impacted by the renovation or demolition activities must be treated as a bulk product waste and properly disposed of if impacted during construction activities unless samples are collected to ascertain the actual concentrations.

3.4 Universal Waste Materials and Other Environmental Concerns

3.4.1 PCB and Di-ethylhexylphthalate (DEHP) Containing Items

A visual inspection for the presence of lighting ballasts and electrical equipment potentially containing PCB's or DEHP was performed within the inspection areas. Lighting ballasts and oil-filled capacitor manufactured after 1979 may have "NO PCB's" stamped on its casing. These are filled with oil which does not contain PCB's but may contain DEHP. Lighting ballasts and Capacitors with date stamps prior to 1979 or no date stamps are assumed to contain PCB's. Lighting ballasts and capacitors labeled as "No PCB's" are assumed to contain DEHP if the date stamp is illegible or non-existent. Electronic ballasts are not assumed to contain PCB's or DEHP.

3.4.2 Mercury Containing Items

During the visual inspection process, fluorescent, metal halide and sodium lamps are assumed to contain mercury vapors. Thermostatic controls, switches, manometers, capacitors and other used electronic components are inventoried during the inspection process.

3.4.3 Used Electronics and Batteries

An inventory of used electronics that may fall under the Universal Waste regulations was developed during the inspection. These materials include but are not limited to lead acid batteries in emergency lighting and exit signs and stored electronic equipment that may contain hazardous or regulated substances. Electronic components such as computers, copy machines, etc that are in use at the time of the inspection are generally not included in the inventory.

3.4.4 Chlorofluorocarbons

Eagle inspected the building for compressor tanks associated with water fountains, portable air conditioning units, the indoor environmental cooling system and walk-in coolers or freezers where applicable. The inspectors also inspected rooftop HVAC units where present. These tanks are all assumed to contain Freon. The size and quantity of tanks are estimated and recorded.

4. INSPECTION RESULTS

4.1 Asbestos Containing Materials

During the course of the building inspection fifty-four (54) bulk samples of suspect ACM were collected and fifty-one (51) samples were analyzed by PLM based on the “stop on first positive” request to the laboratory.

From the fifty-one (51) samples analyzed, the materials listed below were found to be ACM:

- White paper duct insulation above basement plaster ceiling and in wall chases
- Black condensate coating on sink

The white paper duct insulation is associated with the abandoned forced air system. The paper duct insulation was identified on metal ducts above the plaster ceiling in the basement and within limited plaster wall chases on the first and second floors.

The remaining suspect materials were confirmed to be non-ACM.

The summaries of asbestos and non-asbestos materials are presented in Tables I and II respectively. The asbestos analysis laboratory reports are provided in Appendix 2.

Any suspect material not specifically identified in this report as non-ACM should be assumed to contain asbestos unless sample results prove otherwise. Eagle recommends that a project specification for asbestos abatement be prepared to further clarify the type, location and quantity of ACM requiring abatement. This report is not intended to serve as a scope of work or technical specification for asbestos abatement.

All regulated friable and regulated non-friable ACM that will be impacted by renovation activities must be removed prior to or concurrently with building renovations. All regulated friable and regulated non-friable ACM must be removed from the building prior to demolition activities. A State of Connecticut Licensed Asbestos Abatement Contractor must be retained to perform the removal work. Visual inspections and air clearances must be performed within each abatement area at the completion of the abatement work. The visual inspections and air clearances must be performed by a State of Connecticut licensed Asbestos Project Monitor. The abatement areas must meet final visual and air clearance inspection criteria prior to re-occupancy or building renovation/demolition. Re-occupancy air monitoring is required if the building will be re-entered by any person following abatement and prior to demolition. This includes but is not limited to entry for utility disconnects, salvage, equipment removal, etc.

State of Connecticut Regulatory Notification Requirements

The Asbestos Abatement Contractor must submit a notice of asbestos abatement to the State of Connecticut Department of Public Health post marked or hand delivered ten (10) calendar days prior to the commencement of any asbestos abatement activities involving the abatement of greater than ten (10) linear feet or twenty-five (25) square feet of asbestos-containing materials. The asbestos abatement notification satisfies the DPH regulatory requirements for demolition notification. For asbestos abatement projects involving less than ten (10) linear feet or twenty-five (25) square feet of asbestos-containing materials or projects where no regulated asbestos-containing materials are identified, the facility owner or any person who will be conducting demolition must

submit a demolition notification to the State of Connecticut Department of Public Health post marked or hand delivered ten (10) days prior to the commencement of demolition activities.

United States Environmental Protection Agency Notification Requirements

As of December 14, 2017, the facility owner/operator must provide a notification of demolition and renovation under the USEPA National Emission Standard for Hazardous Air Pollutants (NESHAP) regulation 40 CFR Part 61 Subpart M. The facility owner must submit notification to the USEPA for all demolition projects ten (10) working days prior to all demolition projects, which fall under the NESHAP regulation regardless of the presence of asbestos-containing materials. The facility owner must also provide notification to the USEPA for all renovation project ten (10) working days prior to all renovation projects involving greater than one hundred sixty (160) square feet or greater than two hundred sixty (260) linear feet or thirty-five (35) cubic feet of regulated asbestos-containing materials.

State and federal notifications are completely independent of one another and both regulatory agencies must be notified when applicable.

4.2 Lead-based Paint

4.2.1 X-Ray Fluorescence Screen

A total of one hundred forty-six (146) XRF readings were collected during the lead-based paint screen of the building. From the one hundred forty-six (146) readings, fifty-five (55) were found to contain high levels of lead.

The general inventory of surfaces containing high levels of lead include the following:

- Room 0-01 (basement) ceiling beam, steel column, window sash, wall, door components, stairs treads and risers
- Room 0-02 (basement storage) door components and window sash
- Room ST-3 (stairs) floors, ceiling, wood stair components, wall and window components
- Room 1-04 (kitchen) plaster ceiling and walls
- Room 1-05 (women's lavatory) window sash
- Room 1-07 (dining room) window components
- Room 1-08 (living room) window sash
- Room 2-10 (office) window sash
- Room 2-11 (bathroom) ceiling and walls
- Exterior wood siding, soffit, fascia, porch floor, porch ceilings, window casings, window sills, door casings and railing balusters, basement window sashes and drain boot

Additionally, several building materials were determined to contain low levels of lead in paint. Although these levels of lead in paint were less than 1.0 mg/cm², the contractor must perform an exposure assessment on employees during tasks that disturb the painted materials.

The remaining components and surfaces that were tested contain no lead in their respective paint coatings.

The U.S. Department of Labor Occupation Safety and Health Administration (OSHA) regulates lead dust exposure to workers in the construction industry under 29 CFR 1926.62 Lead Exposure in Construction; Interim Final Rule. Currently, OSHA does not define a threshold level of lead in paint that may cause worker exposure. Any detectable level of lead in paint ($>0.0 \text{ mg/cm}^2 \pm 0.3 \text{ mg/cm}^2$ by XRF or $>0.01 \%$ by AAS) requires task specific exposure monitoring. This "initial exposure assessment" must be conducted by trained workers utilizing appropriate personal protective equipment. Exposure assessments must be conducted for each task where painted surfaces or components are disturbed.

Examples of task subject to initial monitoring when detectable levels of lead are identified include but are not limited to surface preparation for repainting, manual demolition of components with detectable levels of lead paint and the welding, cutting or grinding of steel with detectable levels of lead in paint.

A complete inventory of tested building materials is presented in Detailed Reports contained Appendix 3.

4.2.2 Lead Waste Characterization Results

TCLP waste characterization samples were not collected at this time. Following the inspection of the building, the Owner reported that the building may be renovated instead of demolished. TCLP sampling could not be performed because the extent of renovation was not known. If renovation work or building demolition are performed in the future, TCLP sampling will be required to characterize the waste removed from the building.

4.3 PCB Inspection Results Summary

Eagle identified several suspect PCB containing materials that were not tested for PCB content at the building. These potential PCB-containing materials include the following:

- Paints on masonry, wood, metal and plaster components
- Floor tile adhesive
- Window glazing compound – double hung sashes
- Basement window glazing compound
- Asphalt shingle
- Caulk at window sashes
- Caulk at storm screens

These materials will require waste characterization testing prior to building demolition or if they will be impacted by the renovation activities.

4.4 Universal Waste Materials and Other Environmental Concerns

4.4.1 PCB and Di-ethylhexylphthalate (DEHP) Containing Items

There were no PCB containing lighting ballasts identified during the inspection. Four (4) DEHP containing lighting ballasts were identified during the inspection. The ballasts must be removed for proper recycling/incineration prior to demolition of the building or if they will be impacted by renovation activities. Light ballasts that have leaked must be segregated from the non-leaking ballasts. Lighting covers or fixtures stained with dielectric fluid must also be removed for proper disposal.

There were no capacitors potentially containing dielectric fluid identified during the inspection.

Two (2) electronic ballasts were identified during the inspection. No further action is required for the electronic ballasts.

The associated inspection data is provided in Table III.

4.4.2 Mercury Containing Items

Approximately two hundred ninety (290) linear feet of fluorescent light tubes and two (2) mercury containing thermostats were identified during the inspection. The fluorescent light tubes and thermostat must be removed from the building for proper recycling prior to building demolition or if they will be impacted by renovation activities.

The associated inspection data is provided in Table III.

4.4.3 Used Electronics and Batteries

Approximately eight (8) emergency lights containing lead-acid batteries were identified during the inspection. The batteries must be removed from the building for proper recycling prior to building demolition or if they will be impacted by renovation activities.

The associated inspection data is provided in Table III.

4.4.4 Chlorofluorocarbons

There were three (3) window AC units potentially containing a Freon tank identified during the inspection. The Freon must be reclaimed prior to building demolition or if the tanks will become a waste product during renovation activities.

5. COST ESTIMATES

This is a budgetary opinion of cost that is expected to be within -15 to + 30 percent of the actual cost for the complete removal of all identified materials. Eagle Environmental, Inc. has no control over the cost of labor, materials, equipment or services furnished by others, or over the Contractor or Contractors' methods of determining prices, or over competitive bidding or market conditions. Eagle Environmental, Inc.'s opinion of probable cost of abatement are made on the basis of Eagle Environmental, Inc.'s experience and qualifications and represent Eagle Environmental, Inc.'s judgment as an experienced and qualified consultant familiar with the abatement industry; but Eagle Environmental, Inc. cannot and does not guarantee that proposals, bids or actual Total Project or Abatement Cost will not vary from opinions of probable cost prepared by Eagle Environmental, Inc. If, prior to the bidding or negotiating phase, the Owner wishes greater assurance as to Total Project or Abatement Cost, the Owner shall employ an independent cost estimator.

The cost estimates are provided in Appendix 4.

TABLE I

ASBESTOS CONTAINING MATERIALS SUMMARY TABLE

KEY FOR TABLES I and II

* Please utilize the following key for abbreviations used in Tables I and II

| KEY | ANALYTICAL METHODS |
|--|--|
| DNA = DID NOT ANALYZE | PLM PC = EPA 600/R-93/116 QUANTITATION 400 POINT COUNT TEM NOB = NEW YORK ELAP 198.4 METHOD PLM = EPA 600/R-93/116 PS = Previously Sampled EA = Each |
| NAD = NO ASBESTOS DETECTED | |
| F = FRIABLE | |
| NF = NON-FRIABLE | |
| TSI = THERMAL SYSTEMS INSULATION | |
| SURF = SURFACING MATERIAL | |
| MISC = MISCELLANEOUS MATERIAL | |
| SF = SQUARE FEET LF = LINEAR FEET Chrys = Chrysotile Amos = Amosite Anth = Anthophyllite Trem = Tremolite Croc = Crocidolite | BOLD TEXT IN "LOCATION" COLUMN INDICATES SAMPLE LOCATION |

TABLE I
ASBESTOS CONTAINING MATERIALS
SUMMARY TABLE
FORMER RIVER HOUSE
1 MAIN STREET
EAST HADDAM, CONNECTICUT

| LOCATION(S) | MATERIAL TYPE | SAMPLE NUMBER | CATEGORY | BULK SAMPLE ANALYSIS RESULTS | | | | ESTIMATED QUANTITY | F/NF | |
|------------------|--|---------------|----------|------------------------------|--------|-----|-----|--------------------|--------|-----|
| | | | | PLM | PLM PC | TEM | NOB | | | ACM |
| 0-01 | Paper duct insulation - white (above plaster ceiling) | 06-20-RF-01 | TSI | 70% Chrys | | | | YES | 40 SF | F |
| | | 06-20-RF-02 | | DNA | | | | | | |
| | | 06-20-RF-03 | | DNA | | | | | | |
| 0-01 | Paper duct insulation - white (debris on the floor) | 06-20-RF-01 | TSI | 70% Chrys | | | | YES | 3 SF | F |
| | | 06-20-RF-02 | | DNA | | | | | | |
| | | 06-20-RF-03 | | DNA | | | | | | |
| 1-07, 2-12, 2-13 | Paper duct insulation - white (in wall chase) | 06-20-RF-01 | TSI | 70% Chrys | | | | YES | 50 SF | F |
| | | 06-20-RF-02 | | DNA | | | | | | |
| | | 06-20-RF-03 | | DNA | | | | | | |
| 1-04 | Condensate coating on sink - black | 06-20-RF-07A | MISC | 3% Chrys | | | | YES | 1 Sink | NF |
| | | 06-20-RF-08 | | DNA | | | | | | |

TABLE II

NON-ASBESTOS-CONTAINING MATERIALS SUMMARY TABLE

KEY FOR TABLES I and II

* Please utilize the following key for abbreviations used in Tables I and II

| KEY | ANALYTICAL METHODS |
|----------------------------------|--|
| DNA = DID NOT ANALYZE | PLM PC = EPA 600/R-93/116 QUANTITATION 400 POINT COUNT |
| NAD = NO ASBESTOS DETECTED | TEM NOB = NEW YORK ELAP 198.4 METHOD |
| F = FRIABLE | PLM = EPA 600/R-93/116 |
| NF = NON-FRIABLE | PS = Previously Sampled |
| TSI = THERMAL SYSTEMS INSULATION | EA = Each |
| SURF = SURFACING MATERIAL | |
| MISC = MISCELLANEOUS MATERIAL | |
| SF = SQUARE FEET | LF = LINEAR FEET |
| Chrys = Chrysotile | Chrys = Chrysotile |
| Amos = Amosite | Amos = Amosite |
| Anth = Anthophyllite | Anth = Anthophyllite |
| Trem = Tremolite | Trem = Tremolite |
| Croc = Crocidolite | Croc = Crocidolite |

BOLD TEXT IN "LOCATION" COLUMN INDICATES SAMPLE LOCATION

TABLE II
NON - ASBESTOS CONTAINING MATERIALS
SUMMARY TABLE
FORMER RIVER HOUSE
1 MAIN STREET
EAST HADDAM, CONNECTICUT

| LOCATION(S) | MATERIAL TYPE | SAMPLE NUMBER | CATEGORY | BULK SAMPLE ANALYSIS RESULTS | | | |
|---|---------------------------------|---------------|----------|------------------------------|--------|---------|-----|
| | | | | PLM | PLM PC | TEM NOB | ACM |
| 1-04 | Floor tile mastic - brown | 06-20-RF-04 | MISC | NAD | | | NO |
| | | 06-20-RF-05 | | NAD | | | |
| 1-04 | 12" x 12" Floor tile - green | 06-20-RF-06 | MISC | NAD | | | NO |
| | | 06-20-RF-07 | | NAD | | | |
| 1-04 | Formica countertop - white | 06-20-RF-09 | MISC | NAD | | | NO |
| | | 06-20-RF-10 | | NAD | | | |
| 1-05 | Particle board flooring - brown | 06-20-RF-11 | MISC | NAD | | | NO |
| | | 06-20-RF-12 | | NAD | | | |
| ST-03 | Textured ceiling paint | 06-20-RF-13 | SURF | NAD | | | NO |
| | | 06-20-RF-14 | | NAD | | | |
| | | 06-20-RF-15 | | NAD | | | |
| Attic | Blown-in insulation - white | 06-20-RF-16 | MISC | NAD | | | NO |
| | | 06-20-RF-17 | | NAD | | | |
| 0-01, 0-02, 1-07, 1-08, ST-03, 2-11, 2-13 | Plaster rough coat - grey | 06-20-RF-18 | SURF | NAD | | | NO |
| | | 06-20-RF-19 | | NAD | | | |
| | | 06-20-RF-20 | | NAD | | | |
| | | 06-20-RF-21 | | NAD | | | |
| | | 06-20-RF-22 | | NAD | | | |
| | | 06-20-RF-23 | | NAD | | | |
| | | 06-20-RF-24 | | NAD | | | |
| 0-01, 0-02, 1-07, 1-08, ST-03, 2-11, 2-13 | Plaster smooth coat - white | 06-20-RF-25 | SURF | NAD | | | NO |
| | | 06-20-RF-26 | | NAD | | | |
| | | 06-20-RF-27 | | NAD | | | |
| | | 06-20-RF-28 | | NAD | | | |
| | | 06-20-RF-29 | | NAD | | | |
| | | 06-20-RF-30 | | NAD | | | |
| | | 06-20-RF-31 | | NAD | | | |
| B-01, 1-07 | Sheetrock - Type 1 | 06-20-RF-32 | MISC | NAD | | | NO |
| | | 06-20-RF-33 | | NAD | | | |
| 1-04, 1-05 | Sheetrock - Type 2 | 06-20-RF-34 | MISC | NAD | | | NO |
| | | 06-20-RF-35 | | NAD | | | |
| 1-04, 1-05 | Joint compound | 06-20-RF-36 | MISC | NAD | | | NO |
| | | 06-20-RF-37 | | NAD | | | |

TABLE II
NON - ASBESTOS CONTAINING MATERIALS
SUMMARY TABLE
FORMER RIVER HOUSE
1 MAIN STREET
EAST HADDAM, CONNECTICUT

| LOCATION(S) | MATERIAL TYPE | SAMPLE NUMBER | CATEGORY | BULK SAMPLE ANALYSIS RESULTS | | | |
|--------------|---|---------------|----------|------------------------------|--------|---------|-----|
| | | | | PLM | PLM PC | TEM NOB | ACM |
| Façade A | Window glazing compound double hung wood sash - tan | 06-20-RF-38 | MISC | NAD | | | NO |
| | | 06-20-RF-39 | | NAD | | | |
| Façade A | Asphalt and felt paper under clapboard siding | 06-20-RF-40 | MISC | NAD | | | NO |
| | | 06-20-RF-41 | | NAD | | | |
| Façades B, D | Window glazing compound basement wood sash - tan | 06-20-RF-42 | MISC | NAD | | | NO |
| | | 06-20-RF-43 | | NAD | | | |
| Roof 1 | Top layer asphalt shingle - black | 06-20-RF-44 | MISC | NAD | | | NO |
| Roof 1 | Felts below asphalt shingle - black | 06-20-RF-45 | MISC | NAD | | | NO |
| | | 06-20-RF-46 | | NAD | | | |
| Roof 1 | Felts below wood roof shakes - black | 06-20-RF-47 | MISC | NAD | | | NO |
| | | 06-20-RF-48 | | NAD | | | |
| Façade D | Caulk at single hung wood sash | 06-20-RF-49 | MISC | NAD | | | NO |
| | | 06-20-RF-50 | | NAD | | | |
| Façade D | Caulk at storm screen - white | 06-20-RF-51 | MISC | NAD | | | NO |
| | | 06-20-RF-52 | | NAD | | | |
| | | 06-20-RF-53 | MISC | NAD | | | NO |

TABLE III

UNIVERSAL WASTE MATERIALS SUMMARY TABLE

**TABLE III
UNIVERSAL WASTE PRODUCTS
SUMMARY TABLE
FORMER RIVER HOUSE
1 MAIN STREET
EAST HADDAM, CONNECTICUT**

| ROOM | FIXTURE TYPE | BALLAST TYPE | | ELECTRONICS | | THERMO-STATS | LAMPS | | | BATTERIES | | | | |
|--|--------------|--------------|----------|-------------|----------|--------------|------------|------------|----------|-----------|----------|----------|----------|----------|
| | | PCB | DEHP | ELEC. | SPENT | | CAPACITORS | CFCs | LF | ROUND | U SHAPE | FA | ES | ELS |
| 0-02 | 1 | | | | | | | 88 | | | | | | |
| 0-03 | 2,4 | | | | | | | | | | | | | 1 |
| 1-04 | 1 | | | | | | | 40 | | | 1 | 1 | 1 | 1 |
| 1-05 | | | | | | | | | | | | | | |
| 1-06 | 3 | | 2 | | | | | 1 | | | | | | |
| 1-07 | 1 | | | | | | | 32 | | | | | | |
| 1-08 | 4 | | 2 | | | | | 32 | | | | | | |
| 1-09 | 4 | | | 1 | | | | 32 | | | 1 | 1 | 1 | |
| 2-10 | 1,4 | | | | | | | 16 | | | | | | |
| 2-11 | | | | 1 | | | | 1 | | | | | | |
| 2-12 | 1,4 | | | | | | | 16 | | | 1 | 1 | 1 | |
| Hallway | | | | | | | | | | | | | | |
| 3-16 | | | | | | | | 32 | | | | | | |
| Attic | | | | | | | | | | | | | | |
| TOTAL | | | 4 | 2 | 0 | 0 | 3 | 290 | 0 | 0 | 3 | 3 | 3 | 2 |
| NOTES | | | | | | | | | | | | | | |
| KEYS: HALO = Halogen / A/C = Air Conditioner / FA = Fire Alarm / ES = Exit Sign / ELS = Emergency Lighting System | | | | | | | | | | | | | | |
| 1 = DSRAM energy saver 8 bulb - ballast "NO PCB" | | | | | | | | | | | | | | |
| 2 = Circuit boards in server | | | | | | | | | | | | | | |
| 3 = Small 1" ballast (2 in light) rusted unable to read | | | | | | | | | | | | | | |
| 4 = Decorative light fixture fastened to wall | | | | | | | | | | | | | | |
| FIXTURE TYPE | | | | | | | | | | | | | | |
| DESCRIPTION | | | | | | | | | | | | | | |

APPENDIX 1

**FLOOR PLANS AND ROOF PLANS WITH SAMPLE LOCATION
DIAGRAMS**

TOWN OF EAST HADDAM

FORMER RIVER HOUSE

1 MAIN STREET


EAST HADDAM, CONNECTICUT

EAGLE PROJECT NUMBER: 18-144.10T3

INDEX OF DRAWINGS

| | |
|------|--------------|
| BP-1 | BASEMENT |
| FP-1 | FIRST FLOOR |
| FP-2 | SECOND FLOOR |
| FP-3 | ATTIC |
| RP-1 | ROOF |

LOCATION MAP



JULY 13, 2018



EAGLE
Environmental, Inc.

8 SOUTH MAIN STREET, SUITE 3
TERRYVILLE, CONNECTICUT 06786
860-589-8257

SIDE-C




SAMPLE KEY:

6-20-RF-## = ASBESTOS
SAMPLE LOCATION
AND NUMBER

BOLDED SAMPLE NUMBERS
INDICATE PRESENCE OF ASBESTOS IN
CONCENTRATIONS GREATER THAN 1%
WITHIN SAMPLE SET.

SIDE-B

SIDE-D



BASEMENT

NOT TO SCALE

SIDE-A (STREET SIDE)



EAGLE
Environmental, Inc.

8 SOUTH MAIN STREET, SUITE 3
TERRYVILLE, CONNECTICUT 06786
860-589-8257

SHEET NO.

BP-1

DATE: 07/13/2018
PROJECT NO.: 18-144.10T3
DRAWN BY: BB
REVIEWED BY: CL

HAZARDOUS BUILDING MATERIALS INSPECTION
TOWN OF EAST HADDAM
FORMER RIVER HOUSE
1 MAIN STREET
EAST HADDAM, CONNECTICUT

SHEET 1 OF 5

SIDE-C




SAMPLE KEY:

6-20-RF-## = ASBESTOS
SAMPLE LOCATION
AND NUMBER

BOLDED SAMPLE NUMBERS
INDICATE PRESENCE OF ASBESTOS IN
CONCENTRATIONS GREATER THAN 1%
WITHIN SAMPLE SET.

SIDE-B

SIDE-D



FIRST FLOOR

NOT TO SCALE

SIDE-A (STREET SIDE)



EAGLE
Environmental, Inc.

8 SOUTH MAIN STREET, SUITE 3
TERRYVILLE, CONNECTICUT 06786
860-589-8257

SHEET NO.

DATE: 07/13/2018
PROJECT NO.: 18-144.10T3
DRAWN BY: BB
REVIEWED BY: CL

HAZARDOUS BUILDING MATERIALS INSPECTION
TOWN OF EAST HADDAM
FORMER RIVER HOUSE
1 MAIN STREET
EAST HADDAM, CONNECTICUT

FP-1

SHEET 2 OF 5


SIDE-C



SAMPLE KEY:

6-20-RF-## = ASBESTOS
SAMPLE LOCATION
AND NUMBER

BOLDED SAMPLE NUMBERS
INDICATE PRESENCE OF ASBESTOS IN
CONCENTRATIONS GREATER THAN 1%
WITHIN SAMPLE SET.



SIDE-B

SIDE-D

SECOND FLOOR

NOT TO SCALE

SIDE-A (STREET SIDE)



EAGLE
Environmental, Inc.

8 SOUTH MAIN STREET, SUITE 3
TERRYVILLE, CONNECTICUT 06786
860-589-8257

SHEET NO.

DATE: 07/13/2018
PROJECT NO.: 18-144.10T3
DRAWN BY: BB
REVIEWED BY: CL

HAZARDOUS BUILDING MATERIALS INSPECTION
TOWN OF EAST HADDAM
FORMER RIVER HOUSE
1 MAIN STREET
EAST HADDAM, CONNECTICUT

FP-2

SHEET 3 OF 5

SIDE-C




SAMPLE KEY:

6-20-RF-## —●— = ASBESTOS
SAMPLE LOCATION
AND NUMBER

BOLDED SAMPLE NUMBERS
INDICATE PRESENCE OF ASBESTOS IN
CONCENTRATIONS GREATER THAN 1%
WITHIN SAMPLE SET.

SIDE-B



SIDE-D

ATTIC
NOT TO SCALE

SIDE-A (STREET SIDE)



EAGLE
Environmental, Inc.

8 SOUTH MAIN STREET, SUITE 3
TERRYVILLE, CONNECTICUT 06786
860-589-8257

SHEET NO.

DATE: 07/13/2018
PROJECT NO.: 18-144.10T3
DRAWN BY: BB
REVIEWED BY: CL

HAZARDOUS BUILDING MATERIALS INSPECTION
TOWN OF EAST HADDAM
FORMER RIVER HOUSE
1 MAIN STREET
EAST HADDAM, CONNECTICUT

FP-3

SHEET 4 OF 5

SIDE-C




SAMPLE KEY:

6-20-RF-## = ASBESTOS
SAMPLE LOCATION
AND NUMBER

BOLDED SAMPLE NUMBERS
INDICATE PRESENCE OF ASBESTOS IN
CONCENTRATIONS GREATER THAN 1%
WITHIN SAMPLE SET.

SIDE-B

SIDE-D



ROOF 1

6-20-RF-42

6-20-RF-44,45,
46,47,48,49

6-20-RF-40,41

6-20-RF-38

6-20-RF-39

6-20-RF-43

ROOF

NOT TO SCALE

SIDE-A (STREET SIDE)



EAGLE
Environmental, Inc.

8 SOUTH MAIN STREET, SUITE 3
TERRYVILLE, CONNECTICUT 06786
860-589-8257

SHEET NO.

RP-1

SHEET 5 OF 5

DATE: 07/13/2018
PROJECT NO.: 18-144.10T3
DRAWN BY: BB
REVIEWED BY: CL

HAZARDOUS BUILDING MATERIALS INSPECTION
TOWN OF EAST HADDAM
FORMER RIVER HOUSE
1 MAIN STREET
EAST HADDAM, CONNECTICUT


APPENDIX 2

ASBESTOS BULK SAMPLE LABORATORY REPORTS



Bulk Asbestos Analysis

By Polarized Light Microscopy
EPA Method: 600/R-93/116 and 600/M4-82-020



NVLAP Lab Code: 200664-0

Customer: Eagle Environmental, Inc
8 South Main Street
Suite 3
Terryville, CT 06786

Project: Town of E Haddam - River House

Attn: Tammy Poitras

Lab Order ID: 51816455
Analysis ID: 51816455_PLM
Date Received: 6/30/2018
Date Reported: 7/2/2018

| Sample ID | Description | Asbestos | Fibrous Components | Non-Fibrous Components | Attributes |
|---------------|------------------------------------|----------------|--------------------|------------------------|-------------------------------------|
| Lab Sample ID | Lab Notes | | | | Treatment |
| 06-20-RF-01 | Paper duct insulation - white | 70% Chrysotile | | 30% Other | White Fibrous Homogeneous |
| 51816455PLM_1 | | | | | Dissolved |
| 06-20-RF-02 | Paper duct insulation - white | Not Analyzed | | | |
| 51816455PLM_2 | | | | | |
| 06-20-RF-03 | Paper duct insulation - white | Not Analyzed | | | |
| 51816455PLM_3 | | | | | |
| 06-20-RF-04 | Floor tile mastic - brown | None Detected | | 100% Other | Brown Non Fibrous Homogeneous |
| 51816455PLM_4 | | | | | Dissolved |
| 06-20-RF-05 | Floor tile mastic - brown | None Detected | | 100% Other | Brown Non Fibrous Homogeneous |
| 51816455PLM_5 | | | | | Dissolved |
| 06-20-RF-06 | 12" x 12" Floor tile - green | None Detected | | 100% Other | Green Non Fibrous Homogeneous |
| 51816455PLM_6 | | | | | Dissolved |
| 06-20-RF-07 | 12" x 12" Floor tile - green | None Detected | | 100% Other | Green Non Fibrous Homogeneous |
| 51816455PLM_7 | | | | | Dissolved |
| 06-20-RF-07A | Condensate coating on sink - black | 3% Chrysotile | | 97% Other | Black Non Fibrous Homogeneous |
| 51816455PLM_8 | | | | | Dissolved |

Disclaimer: Due to the nature of the EPA 600 method, asbestos may not be detected in samples containing low levels of asbestos. We strongly recommend that analysis of floor tiles, vermiculite, and/or heterogeneous soil samples be conducted by TEM for confirmation of "None Detected" by PLM. This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAL. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government. Analytical uncertainty available upon request. Scientific Analytical Institute participates in the NVLAP Proficiency Testing program. Unless otherwise noted blank sample correction was not performed. Estimated MDL is 0.1%.

Philip Szabo (54)



Analyst

Approved Signatory



Bulk Asbestos Analysis

By Polarized Light Microscopy
EPA Method: 600/R-93/116 and 600/M4-82-020



NVLAP Lab Code: 200664-0

Customer: Eagle Environmental, Inc
8 South Main Street
Suite 3
Terryville, CT 06786

Attn: Tammy Poitras

Lab Order ID: 51816455

Analysis ID: 51816455_PLM

Date Received: 6/30/2018

Date Reported: 7/2/2018

Project: Town of E Haddam - River House

| Sample ID | Description | Asbestos | Fibrous Components | Non-Fibrous Components | Attributes |
|----------------|------------------------------------|---------------|--------------------|------------------------|-------------------------------------|
| Lab Sample ID | Lab Notes | | | | Treatment |
| 06-20-RF-08 | Condensate coating on sink - black | Not Analyzed | | | |
| 51816455PLM_9 | | | | | |
| 06-20-RF-09 | Formica countertop - white | None Detected | 20% Cellulose | 80% Other | White Non Fibrous Homogeneous |
| 51816455PLM_10 | | | | | Ashed, Dissolved |
| 06-20-RF-10 | Formica countertop - white | None Detected | 20% Cellulose | 80% Other | White Non Fibrous Homogeneous |
| 51816455PLM_11 | | | | | Ashed, Dissolved |
| 06-20-RF-11 | Particle board flooring - brown | None Detected | 98% Cellulose | 2% Other | Brown Fibrous Homogeneous |
| 51816455PLM_12 | | | | | Ashed, Dissolved |
| 06-20-RF-12 | Particle board flooring - brown | None Detected | 98% Cellulose | 2% Other | Brown Fibrous Homogeneous |
| 51816455PLM_13 | | | | | Ashed, Dissolved |
| 06-20-RF-13 | Textured ceiling paint | None Detected | | 100% Other | White Non Fibrous Homogeneous |
| 51816455PLM_14 | | | | | Dissolved |
| 06-20-RF-14 | Textured ceiling paint | None Detected | | 100% Other | White Non Fibrous Homogeneous |
| 51816455PLM_15 | | | | | Dissolved |
| 06-20-RF-15 | Textured ceiling paint | None Detected | | 100% Other | White Non Fibrous Homogeneous |
| 51816455PLM_16 | | | | | Dissolved |

Disclaimer: Due to the nature of the EPA 600 method, asbestos may not be detected in samples containing low levels of asbestos. We strongly recommend that analysis of floor tiles, vermiculite, and/or heterogeneous soil samples be conducted by TEM for confirmation of "None Detected" by PLM. This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAL. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government. Analytical uncertainty available upon request. Scientific Analytical Institute participates in the NVLAP Proficiency Testing program. Unless otherwise noted blank sample correction was not performed. Estimated MDL is 0.1%.

Philip Szabo (54)


Analyst

Approved Signatory



Bulk Asbestos Analysis

By Polarized Light Microscopy
EPA Method: 600/R-93/116 and 600/M4-82-020



NVLAP Lab Code: 200664-0

Customer: Eagle Environmental, Inc
8 South Main Street
Suite 3
Terryville, CT 06786

Project: Town of E Haddam - River House

Attn: Tammy Poitras

Lab Order ID: 51816455
Analysis ID: 51816455_PLM
Date Received: 6/30/2018
Date Reported: 7/2/2018

| Sample ID | Description | Asbestos | Fibrous Components | Non-Fibrous Components | Attributes |
|----------------|-----------------------------|---------------|-------------------------|------------------------|------------------------------|
| Lab Sample ID | Lab Notes | | | | Treatment |
| 06-20-RF-16 | Blown-in insulation - white | None Detected | 98% Mineral Wool | 2% Other | White Fibrous Homogeneous |
| 51816455PLM_17 | | | | | Teased, Dissolved |
| 06-20-RF-17 | Blown-in insulation - white | None Detected | 98% Mineral Wool | 2% Other | White Fibrous Homogeneous |
| 51816455PLM_18 | | | | | Teased, Dissolved |
| 06-20-RF-18 | Plaster rough coat - grey | None Detected | 3% Hair 2% Cellulose | 95% Other | Gray Non Fibrous Homogeneous |
| 51816455PLM_19 | | | | | Dissolved |
| 06-20-RF-19 | Plaster rough coat - grey | None Detected | 3% Hair 2% Cellulose | 95% Other | Gray Non Fibrous Homogeneous |
| 51816455PLM_20 | | | | | Dissolved |
| 06-20-RF-20 | Plaster rough coat - grey | None Detected | 3% Hair 2% Cellulose | 95% Other | Gray Non Fibrous Homogeneous |
| 51816455PLM_21 | | | | | Dissolved |
| 06-20-RF-21 | Plaster rough coat - grey | None Detected | 3% Hair 2% Cellulose | 95% Other | Gray Non Fibrous Homogeneous |
| 51816455PLM_22 | | | | | Dissolved |
| 06-20-RF-22 | Plaster rough coat - grey | None Detected | 3% Hair 2% Cellulose | 95% Other | Gray Non Fibrous Homogeneous |
| 51816455PLM_23 | | | | | Dissolved |
| 06-20-RF-23 | Plaster rough coat - grey | None Detected | 3% Hair 2% Cellulose | 95% Other | Gray Non Fibrous Homogeneous |
| 51816455PLM_24 | | | | | Dissolved |

Disclaimer: Due to the nature of the EPA 600 method, asbestos may not be detected in samples containing low levels of asbestos. We strongly recommend that analysis of floor tiles, vermiculite, and/or heterogeneous soil samples be conducted by TEM for confirmation of "None Detected" by PLM. This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAI. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government. Analytical uncertainty available upon request. Scientific Analytical Institute participates in the NVLAP Proficiency Testing program. Unless otherwise noted blank sample correction was not performed. Estimated MDL is 0.1%.

Philip Szabo (54)



Analyst

Approved Signatory



Bulk Asbestos Analysis

By Polarized Light Microscopy
EPA Method: 600/R-93/116 and 600/M4-82-020



Customer: Eagle Environmental, Inc
8 South Main Street
Suite 3
Terryville, CT 06786

Project: Town of E Haddam - River House

Attn: Tammy Poitras

Lab Order ID: 51816455
Analysis ID: 51816455_PLM
Date Received: 6/30/2018
Date Reported: 7/2/2018

| Sample ID | Description | Asbestos | Fibrous Components | Non-Fibrous Components | Attributes |
|----------------|-----------------------------|---------------|-------------------------|------------------------|-------------------------------------|
| Lab Sample ID | Lab Notes | | | | Treatment |
| 06-20-RF-24 | Plaster rough coat - grey | None Detected | 3% Hair 2% Cellulose | 95% Other | Gray Non Fibrous Homogeneous |
| 51816455PLM_25 | | | | | Dissolved |
| 06-20-RF-25 | Plaster smooth coat - white | None Detected | | 100% Other | White Non Fibrous Homogeneous |
| 51816455PLM_26 | | | | | Dissolved |
| 06-20-RF-26 | Plaster smooth coat - white | None Detected | | 100% Other | White Non Fibrous Homogeneous |
| 51816455PLM_27 | | | | | Dissolved |
| 06-20-RF-27 | Plaster smooth coat - white | None Detected | | 100% Other | White Non Fibrous Homogeneous |
| 51816455PLM_28 | | | | | Dissolved |
| 06-20-RF-28 | Plaster smooth coat - white | None Detected | | 100% Other | White Non Fibrous Homogeneous |
| 51816455PLM_29 | | | | | Dissolved |
| 06-20-RF-29 | Plaster smooth coat - white | None Detected | | 100% Other | White Non Fibrous Homogeneous |
| 51816455PLM_30 | | | | | Dissolved |
| 06-20-RF-30 | Plaster smooth coat - white | None Detected | | 100% Other | White Non Fibrous Homogeneous |
| 51816455PLM_31 | | | | | Dissolved |
| 06-20-RF-31 | Plaster smooth coat - white | None Detected | | 100% Other | White Non Fibrous Homogeneous |
| 51816455PLM_32 | | | | | Dissolved |

Disclaimer: Due to the nature of the EPA 600 method, asbestos may not be detected in samples containing low levels of asbestos. We strongly recommend that analysis of floor tiles, vermiculite, and/or heterogeneous soil samples be conducted by TEM for confirmation of "None Detected" by PLM. This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAL. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government. Analytical uncertainty available upon request. Scientific Analytical Institute participates in the NVLAP Proficiency Testing program. Unless otherwise noted blank sample correction was not performed. Estimated MDL is 0.1%.

Philip Szabo (54)


Analyst

Approved Signatory



Bulk Asbestos Analysis

By Polarized Light Microscopy
EPA Method: 600/R-93/116 and 600/M4-82-020



Customer: Eagle Environmental, Inc
8 South Main Street
Suite 3
Terryville, CT 06786

Project: Town of E Haddam - River House

Attn: Tammy Poitras

Lab Order ID: 51816455
Analysis ID: 51816455_PLM
Date Received: 6/30/2018
Date Reported: 7/2/2018

| Sample ID | Description | Asbestos | Fibrous Components | Non-Fibrous Components | Attributes |
|----------------|---|---------------|--------------------|------------------------|-------------------------------------|
| Lab Sample ID | Lab Notes | | | | Treatment |
| 06-20-RF-32 | Sheetrock - Type 1 | None Detected | 5% Cellulose | 95% Other | Gray Non Fibrous Homogeneous |
| 51816455PLM_33 | | | | | Dissolved |
| 06-20-RF-33 | Sheetrock - Type 1 | None Detected | 5% Cellulose | 95% Other | Gray Non Fibrous Homogeneous |
| 51816455PLM_34 | | | | | Dissolved |
| 06-20-RF-34 | Sheetrock - Type 2 | None Detected | 5% Cellulose | 95% Other | Gray Non Fibrous Homogeneous |
| 51816455PLM_35 | | | | | Dissolved |
| 06-20-RF-35 | Sheetrock - Type 2 | None Detected | 5% Cellulose | 95% Other | Gray Non Fibrous Homogeneous |
| 51816455PLM_36 | | | | | Dissolved |
| 06-20-RF-36 | Joint compound | None Detected | | 100% Other | White Non Fibrous Homogeneous |
| 51816455PLM_37 | | | | | Dissolved |
| 06-20-RF-37 | Joint compound | None Detected | | 100% Other | White Non Fibrous Homogeneous |
| 51816455PLM_38 | | | | | Dissolved |
| 06-20-RF-38 | Window glazing compound dbl hung wood sash - tan | None Detected | | 100% Other | Tan Non Fibrous Homogeneous |
| 51816455PLM_39 | | | | | Ashed, Dissolved |
| 06-20-RF-39 | Window glazing compound dbl hung wood sash - tan | None Detected | | 100% Other | Tan Non Fibrous Homogeneous |
| 51816455PLM_40 | | | | | Ashed, Dissolved |

Disclaimer: Due to the nature of the EPA 600 method, asbestos may not be detected in samples containing low levels of asbestos. We strongly recommend that analysis of floor tiles, vermiculite, and/or heterogeneous soil samples be conducted by TEM for confirmation of "None Detected" by PLM. This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAL. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government. Analytical uncertainty available upon request. Scientific Analytical Institute participates in the NVLAP Proficiency Testing program. Unless otherwise noted blank sample correction was not performed. Estimated MDL is 0.1%.

Philip Szabo (54)


Analyst

Approved Signatory



Bulk Asbestos Analysis

By Polarized Light Microscopy
EPA Method: 600/R-93/116 and 600/M4-82-020



NVLAP Lab Code: 200664-0

Customer: Eagle Environmental, Inc
8 South Main Street
Suite 3
Terryville, CT 06786

Project: Town of E Haddam - River House

Attn: Tammy Poitras

Lab Order ID: 51816455
Analysis ID: 51816455_PLM
Date Received: 6/30/2018
Date Reported: 7/2/2018

| Sample ID | Description | Asbestos | Fibrous Components | Non-Fibrous Components | Attributes |
|----------------|--|---------------|--------------------|------------------------|-------------------------------|
| Lab Sample ID | Lab Notes | | | | Treatment |
| 06-20-RF-40 | Asphalt and felt paper under clapboard | None Detected | 70% Cellulose | 30% Other | Black Fibrous Homogeneous |
| 51816455PLM_41 | felt paper only | | | | Ashed, Dissolved |
| 06-20-RF-41 | Asphalt and felt paper under clapboard | None Detected | 70% Cellulose | 30% Other | Black Fibrous Homogeneous |
| 51816455PLM_42 | felt paper only | | | | Ashed, Dissolved |
| 06-20-RF-42 | Window glazing compound basement wd sash - tan | None Detected | | 100% Other | Tan Non Fibrous Homogeneous |
| 51816455PLM_43 | | | | | Ashed, Dissolved |
| 06-20-RF-43 | Window glazing compound basement wd sash - tan | None Detected | | 100% Other | Tan Non Fibrous Homogeneous |
| 51816455PLM_44 | | | | | Ashed, Dissolved |
| 06-20-RF-44 | Top layer asphalt shingle - black | None Detected | 10% Fiber Glass | 90% Other | Black Non Fibrous Homogeneous |
| 51816455PLM_45 | | | | | Dissolved |
| 06-20-RF-45 | Top layer asphalt shingle - black | None Detected | 10% Fiber Glass | 90% Other | Black Non Fibrous Homogeneous |
| 51816455PLM_46 | | | | | Dissolved |
| 06-20-RF-46 | Felts below asphalt shingle - black | None Detected | 70% Cellulose | 30% Other | Black Fibrous Homogeneous |
| 51816455PLM_47 | | | | | Ashed, Dissolved |
| 06-20-RF-47 | Felts below asphalt shingle - black | None Detected | 70% Cellulose | 30% Other | Black Fibrous Homogeneous |
| 51816455PLM_48 | | | | | Ashed, Dissolved |

Disclaimer: Due to the nature of the EPA 600 method, asbestos may not be detected in samples containing low levels of asbestos. We strongly recommend that analysis of floor tiles, vermiculite, and/or heterogeneous soil samples be conducted by TEM for confirmation of "None Detected" by PLM. This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAL. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government. Analytical uncertainty available upon request. Scientific Analytical Institute participates in the NVLAP Proficiency Testing program. Unless otherwise noted blank sample correction was not performed. Estimated MDL is 0.1%.

Philip Szabo (54)

Analyst

Approved Signatory




Bulk Asbestos Analysis

By Polarized Light Microscopy
EPA Method: 600/R-93/116 and 600/M4-82-020



NVLAP Lab Code: 200664-0



Customer: Eagle Environmental, Inc
8 South Main Street
Suite 3
Terryville, CT 06786

Project: Town of E Haddam - River House

Attn: Tammy Poitras

Lab Order ID: 51816455
Analysis ID: 51816455_PLM
Date Received: 6/30/2018
Date Reported: 7/2/2018

| Sample ID | Description | Asbestos | Fibrous Components | Non-Fibrous Components | Attributes |
|----------------|--------------------------------------|---------------|--------------------|------------------------|-------------------------------|
| Lab Sample ID | Lab Notes | | | | Treatment |
| 06-20-RF-48 | Felts below wood roof shakes - black | None Detected | 70% Cellulose | 30% Other | Black Fibrous Homogeneous |
| 51816455PLM_49 | | | | | Ashed, Dissolved |
| 06-20-RF-49 | Felts below wood roof shakes - black | None Detected | 70% Cellulose | 30% Other | Black Fibrous Homogeneous |
| 51816455PLM_50 | | | | | Ashed, Dissolved |
| 06-20-RF-50 | Caulk at single hung wood sash | None Detected | | 100% Other | White Non Fibrous Homogeneous |
| 51816455PLM_51 | | | | | Ashed, Dissolved |
| 06-20-RF-51 | Caulk at single hung wood sash | None Detected | | 100% Other | White Non Fibrous Homogeneous |
| 51816455PLM_52 | | | | | Ashed, Dissolved |
| 06-20-RF-52 | caulk at storm screen - white | None Detected | | 100% Other | White Non Fibrous Homogeneous |
| 51816455PLM_53 | | | | | Ashed, Dissolved |
| 06-20-RF-53 | caulk at storm screen - white | None Detected | | 100% Other | White Non Fibrous Homogeneous |
| 51816455PLM_54 | | | | | Ashed, Dissolved |

Disclaimer: Due to the nature of the EPA 600 method, asbestos may not be detected in samples containing low levels of asbestos. We strongly recommend that analysis of floor tiles, vermiculite, and/or heterogeneous soil samples be conducted by TEM for confirmation of "None Detected" by PLM. This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAL. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government. Analytical uncertainty available upon request. Scientific Analytical Institute participates in the NVLAP Proficiency Testing program. Unless otherwise noted blank sample correction was not performed. Estimated MDL is 0.1%.

Philip Szabo (54)

Analyst

Approved Signatory

51 samples

51816455

| | | | |
|---|--|---|---------------------------|
| Client: Eagle Environmental, Inc Tammy Poitras 8 South Main Street 860-589-8257 x110 860-585-7034 tpoitras@eagleenviro.com | Instructions: Use Column "B" for your contact info To See an Example Click the bottom Example Tab. Enter samples between "<<" and ">>" Begin Samples with a "<<" above the first sample and end with a ">>" below the last sample. Only Enter your data on the first sheet "Sheet1" | Project: Town of E Haddam - River House | Sample Description |
| Client Notes: Stop on 1st Positive | Note: Data 1 and Data 2 are optional fields that do not show up on the official report; however they will be included in the electronic data returned to you to facilitate your reintegration of the report data. | Stop on 1st Positive | Sample Description |
| P.O. #: 18-144.10T3 | Date Submitted: 6/22/2018 0:00 | Analysis: PLM: Bulk 600/R-93/116 | Sample Description |
| Turn/Around Time: 24 Hours | | | Sample Description |



**4604 Dundas Drive
Greensboro, NC 27407
Phone: 336.292.3888
Fax: 336.292.3313
Email: lab@sailab.com**

| Sample Number | Data 1 | Sample Description | Data 2 |
|---------------|--------|--------------------|--------|
|---------------|--------|--------------------|--------|

| Sample Number | Data 1 | Sample Description | Data 2 |
|---------------|--------|------------------------------------|------------------------------------|
| 06-20-RF-01 | B-01 | Paper duct insulation - white | [Enter data of your choosing here] |
| 06-20-RF-02 | B-01 | Paper duct insulation - white | [Enter data of your choosing here] |
| 06-20-RF-03 | B-01 | Paper duct insulation - white | [Enter data of your choosing here] |
| 06-20-RF-04 | 1-04 | Floor tile mastic - brown | [Enter data of your choosing here] |
| 06-20-RF-05 | 1-04 | Floor tile mastic - brown | [Enter data of your choosing here] |
| 06-20-RF-06 | 1-04 | 12" x 12" Floor tile - green | [Enter data of your choosing here] |
| 06-20-RF-07 | 1-04 | 12" x 12" Floor tile - green | [Enter data of your choosing here] |
| 06-20-RF-07A | 1-04 | Condensate coating on sink - black | [Enter data of your choosing here] |
| 06-20-RF-08 | 1-04 | Condensate coating on sink - black | [Enter data of your choosing here] |
| 06-20-RF-09 | 1-04 | Formica countertop - white | [Enter data of your choosing here] |
| 06-20-RF-10 | 1-04 | Formica countertop - white | [Enter data of your choosing here] |
| 06-20-RF-11 | 1-05 | Particle board flooring - brown | [Enter data of your choosing here] |
| 06-20-RF-12 | 1-05 | Particle board flooring - brown | [Enter data of your choosing here] |
| 06-20-RF-13 | ST-03 | Textured ceiling paint | [Enter data of your choosing here] |
| 06-20-RF-14 | ST-03 | Textured ceiling paint | [Enter data of your choosing here] |
| 06-20-RF-15 | ST-03 | Textured ceiling paint | [Enter data of your choosing here] |
| 06-20-RF-16 | Attic | Blown-in insulation - white | [Enter data of your choosing here] |
| 06-20-RF-17 | Attic | Blown-in insulation - white | [Enter data of your choosing here] |

Relinquished By [Signature]

Accepted Rejected

Received By [Signature] 6/30 10:39A

APPENDIX 3

XRF LEAD-BASED PAINT INSPECTION REPORTS

LEAD PAINT INSPECTION REPORT

REPORT NUMBER: S#03611 - 06/20/18 09:32

INSPECTION FOR: Mr. Ronald Turner, Direc. of Operation
Town of East Haddam
26 Plains Road, PO Box 401
Modus, Connecticut 06469

PERFORMED AT: River House
1 Main Street
East Haddam, CT

INSPECTION DATE: 06/20/18

INSTRUMENT TYPE: R M D
MODEL LPA-1
XRF TYPE ANALYZER
Serial Number: 03611

ACTION LEVEL: 1.0 mg/cm²

OPERATOR LICENSE: 002282

Lead Based-Paint Screen

SIGNED: 

Alexis St. Hilaire
Lead Inspector
Eagle Environmental, Inc.
8 South Main Street, Suite #3
Terryville, CT 06786

Date: 6/20/18

SUMMARY REPORT OF LEAD PAINT INSPECTION FOR: Mr. Ronald Turner, Direc. of Operation

Inspection Date: 06/20/18 River House
 Report Date: 6/20/2018 1 Main Street
 Abatement Level: 1.0 East Haddam, CT
 Report No. S#03611 - 06/20/18 09:32
 Total Readings: 146 Actionable: 55
 Job Started: 06/20/18 09:32
 Job Finished: 06/20/18 11:14

| Reading No. | Wall | Structure | Location | Member | Paint Cond | Substrate | Color | Lead (mg/cm ²) | Mode |
|--------------------------------------|------|------------|----------|-----------|------------|-----------|-------|----------------------------|------|
| Exterior Room 001 Porch 1A | | | | | | | | | |
| 109 | A | Siding | Rgt | | D | Wood | white | >9.9 | QM |
| 118 | A | Soffit | Rgt | | D | Wood | white | 9.7 | QM |
| 119 | A | Fascia | Rgt | | D | Wood | white | 4.1 | QM |
| 115 | A | Floor | Rgt | | D | Wood | blue | 1.0 | QM |
| 116 | A | Ceiling | Rgt | | D | Wood | white | >9.9 | QM |
| 117 | A | Ceiling | Rgt | Beam | D | Wood | white | >9.9 | QM |
| 110 | A | Window | Rgt | Casing | D | Wood | white | >9.9 | QM |
| 111 | A | Window | Rgt | Sill | D | Wood | white | >9.9 | QM |
| 120 | A | Door | Rgt | Casing | D | Wood | white | >9.9 | QM |
| 114 | A | Railing | Rgt | Balusters | D | Wood | white | >9.9 | QM |
| Exterior Room 002 Facade B | | | | | | | | | |
| 129 | B | base win | Lft | Sash | D | Wood | blue | 2.9 | QM |
| 127 | B | drain boot | Rgt | | I | Metal | white | 8.5 | QM |
| Exterior Room 003 Facade C | | | | | | | | | |
| 131 | C | Window | Rgt | Casing | D | Wood | white | >9.9 | QM |
| 132 | C | Window | Rgt | Sill | D | Wood | white | >9.9 | QM |
| Exterior Room 004 Facade D | | | | | | | | | |
| 133 | D | Siding | Lft | | D | Wood | white | 1.6 | QM |
| 135 | D | Ceiling | Rgt | | D | Wood | white | >9.9 | QM |
| 136 | D | Ceiling | Rgt | Beam | D | Wood | white | >9.9 | QM |
| Interior Room 001 Basement | | | | | | | | | |
| 007 | - | Ceiling | Rgt | Beam | D | Wood | white | 1.0 | QM |
| 004 | - | Column | Ctr | | D | Steel | white | >9.9 | QM |
| 009 | B | Window | Rgt | Sash | D | Wood | white | 2.3 | QM |
| 006 | C | Wall | Rgt | | D | Wood | white | 1.6 | QM |
| 012 | D | Door | Rgt | door | D | Wood | green | >9.9 | QM |
| 013 | D | Door | Rgt | Casing | D | Wood | blue | 6.2 | QM |
| 014 | D | Door | Rgt | Jamb | D | Wood | green | 2.4 | QM |
| 015 | D | Door | Rgt | Stop | D | Wood | green | 2.5 | QM |
| 010 | D | Stairs | Lft | Treads | D | Wood | blue | 8.1 | QM |
| 011 | D | Stairs | Lft | Risers | D | Wood | blue | 8.5 | QM |
| Interior Room 002 base storag | | | | | | | | | |
| 016 | A | Door | Ctr | door | D | Wood | white | 1.7 | QM |
| 017 | A | Door | Ctr | Jamb | D | Wood | white | 1.9 | QM |
| 018 | A | Door | Ctr | Stop | D | Wood | white | 6.2 | QM |

SUMMARY REPORT OF LEAD PAINT INSPECTION FOR: Mr. Ronald Turner, Direc. of Operation

| Reading No. | Wall | Structure | Location | Member | Paint Cond | Substrate | Color | Lead (mg/cm ²) | Mode |
|------------------------------|------|-----------|----------|------------|------------|-----------|-------|----------------------------|------|
| 019 | D | Window | Ctr | Sash | D | Wood | white | 3.6 | QM |
| Interior Room 003 Stairs | | | | | | | | | |
| 101 | - | Floor | Lft | | D | Wood | blue | 3.5 | QM |
| 022 | - | Floor | Ctr | | D | Wood | blue | 6.9 | QM |
| 025 | - | Ceiling | Ctr | | D | Plaster | white | 6.4 | QM |
| 104 | - | Stairs | Lft | Stringers | D | Wood | blue | 5.6 | QM |
| 102 | - | Stairs | Lft | Treads | D | Wood | blue | 9.2 | QM |
| 103 | - | Stairs | Lft | Risers | D | Wood | blue | 9.1 | QM |
| 024 | - | Stairs | Ctr | Risers | D | Wood | blue | 3.1 | QM |
| 021 | A | Wall | L Ctr | | D | Wood | white | 3.3 | QM |
| 020 | A | Wall | U Ctr | | D | Plaster | green | 7.0 | QM |
| 026 | B | Door | Lft | Casing | D | Wood | stain | 3.4 | QM |
| 080 | D | Window | Ctr | ext. jamb | D | Wood | white | 9.0 | QM |
| 081 | D | Window | Ctr | ext. stop | D | Wood | white | >9.9 | QM |
| 077 | D | Window | Ctr | Sash | D | Wood | stain | >9.9 | QM |
| Interior Room 004 Kitchen | | | | | | | | | |
| 035 | - | Ceiling | Ctr | | I | Plaster | white | >9.9 | QM |
| 030 | A | Wall | Ctr | | I | Plaster | white | >9.9 | QM |
| Interior Room 005 Womens Lav | | | | | | | | | |
| 041 | C | Window | Ctr | Sash | D | Wood | white | 6.9 | QM |
| Interior Room 007 Dining Rm | | | | | | | | | |
| 054 | C | Window | Ctr | ext. jamb | D | Wood | white | >9.9 | QM |
| 055 | C | Window | Ctr | ext. stop | D | Wood | white | >9.9 | QM |
| 051 | C | Window | Ctr | Sash | D | Wood | white | 2.7 | QM |
| 053 | C | Window | Ctr | Part. bead | D | Wood | white | >9.9 | QM |
| Interior Room 008 Living Rm | | | | | | | | | |
| 066 | A | Window | Rgt | Sash | I | Wood | white | 7.7 | QM |
| Interior Room 010 L office | | | | | | | | | |
| 087 | A | Window | Ctr | Sash | D | Wood | stain | 1.4 | QM |
| Interior Room 011 Bathroom | | | | | | | | | |
| 096 | - | Ceiling | Lft | | I | Plaster | white | 8.6 | QM |
| 094 | B | Wall | Lft | | I | Plaster | N/A | 7.3 | QM |
| | | wallpaper | | | | | | | |

---- End of Readings ----

DETAILED REPORT OF LEAD PAINT INSPECTION FOR: Mr. Ronald Turner, Direc. of Operation

Inspection Date: 06/20/18 River House
 Report Date: 6/20/2018 1 Main Street
 Abatement Level: 1.0 East Haddam, CT
 Report No. S#03611 - 06/20/18 09:32
 Total Readings: 146
 Job Started: 06/20/18 09:32
 Job Finished: 06/20/18 11:14

| Reading No. | Wall | Structure | Location | Member | Paint Cond | Substrate | Color | Lead (mg/cm ²) | Mode |
|-----------------------------------|------|-------------|----------|-------------|------------|-----------|-------|----------------------------|------|
| Exterior Room 001 Porch 1A | | | | | | | | | |
| 109 | A | Siding | Rgt | | D | Wood | white | >9.9 | QM |
| 118 | A | Soffit | Rgt | | D | Wood | white | 9.7 | QM |
| 119 | A | Fascia | Rgt | | D | Wood | white | 4.1 | QM |
| 115 | A | Floor | Rgt | | D | Wood | blue | 1.0 | QM |
| 116 | A | Ceiling | Rgt | | D | Wood | white | >9.9 | QM |
| 117 | A | Ceiling | Rgt | Beam | D | Wood | white | >9.9 | QM |
| 110 | A | Window | Rgt | Casing | D | Wood | white | >9.9 | QM |
| 111 | A | Window | Rgt | Sill | D | Wood | white | >9.9 | QM |
| 120 | A | Door | Rgt | Casing | D | Wood | white | >9.9 | QM |
| 121 | A | Door | Rgt | Stop | D | Wood | white | -0.1 | QM |
| 122 | A | Door | Rgt | door | D | Wood | white | 0.0 | QM |
| 123 | A | Door | Rgt | Kickplate | D | Wood | white | -0.1 | QM |
| 124 | A | Stairs | Rgt | Treads | D | Wood | blue | 0.1 | QM |
| 125 | A | Stairs | Rgt | Risers | D | Wood | white | -0.3 | QM |
| 114 | A | Railing | Rgt | Balusters | D | Wood | white | >9.9 | QM |
| 113 | A | Railing | Rgt | Railing | D | Wood | white | -0.2 | QM |
| 112 | A | Column | Rgt | | D | Wood | white | -0.1 | QM |
| Exterior Room 002 Facade B | | | | | | | | | |
| 128 | B | base win | Lft | Casing | D | Wood | blue | 0.2 | QM |
| 129 | B | base win | Lft | Sash | D | Wood | blue | 2.9 | QM |
| 130 | B | base win | Lft | Sill | D | Wood | blue | 0.6 | QM |
| 126 | B | Lattice | Rgt | | I | Wood | white | -0.1 | QM |
| 127 | B | drain boot | Rgt | | I | Metal | white | 8.5 | QM |
| Exterior Room 003 Facade C | | | | | | | | | |
| 131 | C | Window | Rgt | Casing | D | Wood | white | >9.9 | QM |
| 132 | C | Window | Rgt | Sill | D | Wood | white | >9.9 | QM |
| Exterior Room 004 Facade D | | | | | | | | | |
| 133 | D | Siding | Lft | | D | Wood | white | 1.6 | QM |
| 134 | D | Attic Hatch | Lft | Door | D | Wood | white | -0.2 | QM |
| 135 | D | Ceiling | Rgt | | D | Wood | white | >9.9 | QM |
| 136 | D | Ceiling | Rgt | Beam | D | Wood | white | >9.9 | QM |
| 142 | D | Window | Rgt | Casing | I | Wood | white | -0.2 | QM |
| 143 | D | Window | Rgt | Sash | I | Wood | white | -0.2 | QM |
| 139 | D | Door | Rgt | door | I | Wood | white | 0.0 | QM |
| 140 | D | Door | Rgt | Door Casing | I | Wood | white | -0.2 | QM |
| 141 | D | Door | Rgt | Threshold | D | Wood | blue | 0.1 | QM |
| 138 | D | Railing | Rgt | Balusters | D | Metal | black | 0.2 | QM |
| 137 | D | Railing | Rgt | Railing | D | Metal | black | 0.1 | QM |

DETAILED REPORT OF LEAD PAINT INSPECTION FOR: Mr. Ronald Turner, Direc. of Operation

| Reading No. | Wall | Structure | Location | Member | Paint Cond | Substrate | Color | Lead (mg/cm ²) | Mode |
|-------------------------------|------|-----------|----------|------------|------------|-----------|-------|----------------------------|------|
| Interior Room 001 Basement | | | | | | | | | |
| 007 | - | Ceiling | Rgt | Beam | D | Wood | white | 1.0 | QM |
| 004 | - | Column | Ctr | | D | Steel | white | >9.9 | QM |
| 008 | B | Wall | Rgt | | D | Concrete | white | 0.0 | QM |
| 009 | B | Window | Rgt | Sash | D | Wood | white | 2.3 | QM |
| 005 | C | Chimney | Ctr | | D | Brick | white | 0.1 | QM |
| 006 | C | Wall | Rgt | | D | Wood | white | 1.6 | QM |
| 012 | D | Door | Rgt | door | D | Wood | green | >9.9 | QM |
| 013 | D | Door | Rgt | Casing | D | Wood | blue | 6.2 | QM |
| 014 | D | Door | Rgt | Jamb | D | Wood | green | 2.4 | QM |
| 015 | D | Door | Rgt | Stop | D | Wood | green | 2.5 | QM |
| 010 | D | Stairs | Lft | Treads | D | Wood | blue | 8.1 | QM |
| 011 | D | Stairs | Lft | Risers | D | Wood | blue | 8.5 | QM |
| Interior Room 002 base storag | | | | | | | | | |
| 016 | A | Door | Ctr | door | D | Wood | white | 1.7 | QM |
| 017 | A | Door | Ctr | Jamb | D | Wood | white | 1.9 | QM |
| 018 | A | Door | Ctr | Stop | D | Wood | white | 6.2 | QM |
| 019 | D | Window | Ctr | Sash | D | Wood | white | 3.6 | QM |
| Interior Room 003 Stairs | | | | | | | | | |
| 101 | - | Floor | Lft | | D | Wood | blue | 3.5 | QM |
| 022 | - | Floor | Ctr | | D | Wood | blue | 6.9 | QM |
| 025 | - | Ceiling | Ctr | | D | Plaster | white | 6.4 | QM |
| 083 | - | Ceiling | Ctr | | I | Plaster | white | 0.4 | QM |
| 104 | - | Stairs | Lft | Stringers | D | Wood | blue | 5.6 | QM |
| 102 | - | Stairs | Lft | Treads | D | Wood | blue | 9.2 | QM |
| 103 | - | Stairs | Lft | Risers | D | Wood | blue | 9.1 | QM |
| 023 | - | Stairs | Ctr | Treads | D | Wood | blue | 0.1 | QM |
| 024 | - | Stairs | Ctr | Risers | D | Wood | blue | 3.1 | QM |
| 075 | - | Stairs | Rgt | Stringers | D | Wood | stain | 0.1 | QM |
| 073 | - | Stairs | Rgt | Treads | D | Wood | stain | -0.2 | QM |
| 074 | - | Stairs | Rgt | Risers | D | Wood | stain | -0.2 | QM |
| 070 | - | Stairs | Rgt | Newel post | D | Wood | stain | -0.2 | QM |
| 072 | - | Railing | Rgt | Balusters | D | Wood | stain | 0.1 | QM |
| 071 | - | Railing | Rgt | Railing | D | Wood | stain | -0.2 | QM |
| 021 | A | Wall | L Ctr | | D | Wood | white | 3.3 | QM |
| 105 | A | Wall | Rgt | | D | Plaster | white | -0.1 | QM |
| 020 | A | Wall | U Ctr | | D | Plaster | green | 7.0 | QM |
| 026 | B | Door | Lft | Casing | D | Wood | stain | 3.4 | QM |
| 027 | B | Door | Lft | Jamb | D | Wood | white | -0.1 | QM |
| 028 | B | Door | Lft | Stop | D | Wood | stain | 0.0 | QM |
| 029 | B | Door | Lft | door | D | Wood | stain | -0.3 | QM |
| 076 | D | Window | Ctr | Casing | D | Wood | stain | -0.2 | QM |
| 078 | D | Window | Ctr | Jamb | D | Wood | stain | -0.2 | QM |
| 080 | D | Window | Ctr | ext. jamb | D | Wood | white | 9.0 | QM |
| 081 | D | Window | Ctr | ext. stop | D | Wood | white | >9.9 | QM |
| 077 | D | Window | Ctr | Sash | D | Wood | stain | >9.9 | QM |

DETAILED REPORT OF LEAD PAINT INSPECTION FOR: Mr. Ronald Turner, Direc. of Operation

| Reading No. | Wall | Structure | Location | Member | Paint Cond | Substrate | Color | Lead (mg/cm ²) | Mode |
|------------------------------|------|-----------|----------|------------|------------|-----------|-------|----------------------------|------|
| 082 | D | Window | Ctr | Sill | D | Wood | stain | -0.2 | QM |
| 079 | D | Window | Ctr | Part. bead | D | Wood | white | -0.2 | QM |
| Interior Room 004 Kitchen | | | | | | | | | |
| 035 | - | Ceiling | Ctr | | I | Plaster | white | >9.9 | QM |
| 030 | A | Wall | Ctr | | I | Plaster | white | >9.9 | QM |
| 034 | D | Ceiling | Ctr | Beam | I | Wood | stain | -0.2 | QM |
| 031 | D | Window | Ctr | Casing | I | Wood | stain | -0.3 | QM |
| 032 | D | Window | Ctr | Stop | I | Wood | stain | 0.3 | QM |
| 033 | D | Window | Ctr | Sill | I | Wood | stain | -0.2 | QM |
| Interior Room 005 Womens Lav | | | | | | | | | |
| 043 | - | Ceiling | Rgt | | D | Plaster | white | 0.0 | QM |
| 036 | A | Wall | Lft | | D | Plaster | N/A | -0.1 | QM |
| | | wallpaper | | | | | | | |
| 039 | C | Baseboard | Ctr | | D | Wood | white | -0.1 | QM |
| 040 | C | Window | Ctr | Casing | D | Wood | white | 0.0 | QM |
| 041 | C | Window | Ctr | Sash | D | Wood | white | 6.9 | QM |
| 042 | C | Column | Rgt | | D | Wood | white | 0.1 | QM |
| 037 | D | Door | Ctr | Casing | D | Wood | white | 0.0 | QM |
| 038 | D | Door | Ctr | door | D | Wood | stain | 0.0 | QM |
| 044 | D | Door | Rgt | Threshold | D | Wood | stain | -0.3 | QM |
| Interior Room 006 Men's Lav | | | | | | | | | |
| 047 | - | Ceiling | Ctr | | I | Plaster | white | 0.2 | QM |
| 045 | D | Wall | Rgt | | I | Plaster | N/A | -0.4 | QM |
| | | wallpaper | | | | | | | |
| 046 | D | Baseboard | Rgt | | D | Wood | white | -0.1 | QM |
| Interior Room 007 Dining Rm | | | | | | | | | |
| 050 | - | Floor | Rgt | | D | Wood | stain | 0.1 | QM |
| 048 | A | Wall | Rgt | | I | Plaster | white | -0.1 | QM |
| 049 | A | Baseboard | Rgt | | D | Wood | white | 0.0 | QM |
| 059 | A | Door | Ctr | Casing | I | Wood | white | 0.0 | QM |
| 060 | A | Door | Ctr | door | I | Wood | stain | -0.2 | QM |
| 061 | A | Door | Ctr | Jamb | D | Wood | stain | 0.1 | QM |
| 052 | C | Window | Ctr | Jamb | D | Wood | stain | -0.1 | QM |
| 054 | C | Window | Ctr | ext. jamb | D | Wood | white | >9.9 | QM |
| 055 | C | Window | Ctr | ext. stop | D | Wood | white | >9.9 | QM |
| 051 | C | Window | Ctr | Sash | D | Wood | white | 2.7 | QM |
| 056 | C | Window | Ctr | Sill | D | Wood | white | 0.0 | QM |
| 053 | C | Window | Ctr | Part. bead | D | Wood | white | >9.9 | QM |
| 057 | D | Cabinet | Ctr | Casing | D | Wood | white | 0.1 | QM |
| 058 | D | Cabinet | Ctr | Door | D | Wood | white | -0.2 | QM |
| Interior Room 008 Living Rm | | | | | | | | | |
| 065 | - | Floor | Rgt | | I | Wood | stain | -0.2 | QM |
| 062 | A | Ceiling | Ctr | | I | Plaster | white | -0.1 | QM |
| 066 | A | Window | Rgt | Sash | I | Wood | white | 7.7 | QM |

DETAILED REPORT OF LEAD PAINT INSPECTION FOR: Mr. Ronald Turner, Direc. of Operation

| Reading No. | Wall | Structure | Location | Member | Paint Cond | Substrate | Color | Lead (mg/cm ²) | Mode |
|-------------------------------|------|-----------|----------|-----------|------------|-----------|-------|----------------------------|------|
| 063 | B | Wall | Rgt | | I | Plaster | white | 0.0 | QM |
| 064 | B | Baseboard | Rgt | | I | Wood | white | 0.1 | QM |
| Interior Room 009 Front Entry | | | | | | | | | |
| 068 | A | Door | Rgt | Casing | I | Wood | white | -0.2 | QM |
| 069 | A | Door | Rgt | door | D | Wood | stain | -0.2 | QM |
| 067 | D | Wall | Lft | | I | Plaster | white | -0.3 | QM |
| Interior Room 010 L office | | | | | | | | | |
| 086 | - | Floor | Rgt | | D | Wood | stain | -0.2 | QM |
| 093 | - | Ceiling | Lft | | D | Plaster | white | -0.1 | QM |
| 084 | A | Wall | Rgt | | D | Plaster | blue | -0.1 | QM |
| 087 | A | Window | Ctr | Sash | D | Wood | stain | 1.4 | QM |
| 085 | B | Baseboard | Rgt | | I | Wood | stain | 0.0 | QM |
| 088 | C | Door | Lft | Casing | D | Wood | stain | -0.2 | QM |
| 089 | C | Door | Lft | Jamb | D | Wood | stain | -0.1 | QM |
| 090 | C | Door | Lft | Stop | D | Wood | white | 0.1 | QM |
| 091 | C | Door | Lft | Threshold | D | Wood | blue | -0.4 | QM |
| 092 | C | Door | Lft | door | D | Wood | white | -0.1 | QM |
| Interior Room 011 Bathroom | | | | | | | | | |
| 096 | - | Ceiling | Lft | | I | Plaster | white | 8.6 | QM |
| 094 | B | Wall | Lft | | I | Plaster | N/A | 7.3 | QM |
| | | wallpaper | | | | | | | |
| 095 | B | Baseboard | Lft | | I | Wood | white | 0.1 | QM |
| 097 | D | Cabinet | Lft | Door | I | Wood | white | 0.2 | QM |
| Interior Room 012 R office | | | | | | | | | |
| 099 | - | Floor | Lft | | I | Wood | stain | -0.2 | QM |
| 100 | - | Ceiling | Lft | | I | Plaster | white | 0.0 | QM |
| 098 | C | Wall | Lft | | I | Plaster | blue | 0.0 | QM |
| Interior Room 013 Attic | | | | | | | | | |
| 106 | - | Floor | Rgt | | D | Wood | stain | -0.2 | QM |
| 107 | - | Ceiling | Rgt | Beam | I | Wood | stain | -0.1 | QM |
| 108 | - | Ceiling | Rgt | Ceiling | I | Wood | stain | -0.2 | QM |
| Calibration Readings | | | | | | | | | |
| 001 | | | | | | | | 0.9 | TC |
| 002 | | | | | | | | 0.8 | TC |
| 003 | | | | | | | | 0.9 | TC |
| 144 | | | | | | | | 0.9 | TC |
| 145 | | | | | | | | 0.9 | TC |
| 146 | | | | | | | | 0.9 | TC |

----- End of Readings -----

APPENDIX 4

ABATEMENT AND CONSULTING COST ESTIMATES

HAZARDOUS MATERIALS ABATEMENT AND CONSULTING COST ESTIMATES

FORMER RIVER HOUSE

1 MAIN STREET

EAST HADDAM, CONNECTICUT

ESTIMATE INCLUDES COMPLETE REMOVAL OF ALL IDENTIFIED MATERIALS. CONSULTING FEES MAY BE REDUCED IF COMBINED WITH REMAINING 2 BUILDINGS AT THE SITE

ASBESTOS ABATEMENT COST ESTIMATE

| MATERIAL | QUANTITY | UNIT COST | TOTAL COST |
|---|----------|--------------|-------------|
| PAPER DUCT INSULATION IN WALLS/CEILINGS | 90 | \$ 65.00 SF | \$ 5,850.00 |
| PAPER DUCT INSULATION DEBRIS ON FLOOR | 3 | \$ 150.00 SF | \$ 450.00 |
| SINK UNDERCOATING | 1 | \$ 100.00 EA | \$ 100.00 |
| SUBTOTAL | | | \$ 6,400.00 |
| ASBESTOS ABATEMENT CONTINGENCY | | | \$ 640.00 |
| ASBESTOS TOTAL | | | \$ 7,040.00 |

LEAD BASED PAINT COST ESTIMATE

MATERIAL: RENOVATION/DEMOLITION SCOPE AND TCLP TESTING REQUIRED PRIOR TO DEVELOPING FINAL LEAD ABATEMENT SCOPE OF WORK

| MATERIAL | QUANTITY | UNIT COST | TOTAL COST |
|-----------------------------|----------|------------------|--------------|
| LEAD BASED PAINT ALLOWANCE | 1 | \$ 12,000.00 SUM | \$ 12,000.00 |
| SUBTOTAL | | | \$ 12,000.00 |
| LEAD DEMOLITION CONTINGENCY | | | \$ 1,200.00 |
| LEAD DEMOLITION TOTAL | | | \$ 13,200.00 |

UNIVERSAL WASTE ABATEMENT COST ESTIMATE

| MATERIAL | QUANTITY | UNIT COST | TOTAL COST |
|---------------------------------------|----------|---------------|-------------|
| LIGHT BALLAST DISPOSAL | 4 | \$ 5.00 EACH | \$ 20.00 |
| LIGHT TUBES DISPOSAL | 290 | \$ 2.00 LF | \$ 580.00 |
| LEAD ACID BATTERIES DISPOSAL | 8 | \$ 5.00 EACH | \$ 40.00 |
| THERMOSTAT DISPOSAL | 2 | \$ 5.00 EACH | \$ 10.00 |
| LABOR | 1 | \$ 500.00 DAY | \$ 500.00 |
| SUBTOTAL | | | \$ 1,150.00 |
| UNIVERSAL WASTE ABATEMENT CONTINGENCY | | | \$ 287.50 |
| UNIVERSAL WASTE TOTAL | | | \$ 1,437.50 |

CHLOROFLUOROCARBONS ABATEMENT COST ESTIMATE

| MATERIAL | QUANTITY | UNIT COST | TOTAL COST |
|---|----------|----------------|------------|
| AC UNITS | 3 | \$ 100.00 EACH | \$ 300.00 |
| LABOR | 1 | \$ 500.00 EACH | \$ 500.00 |
| SUBTOTAL | | | \$ 800.00 |
| CHLOROFLUOROCARBONS ABATEMENT CONTINGENCY | | | \$ 80.00 |
| CHLOROFLUOROCARBONS TOTAL | | | \$ 880.00 |

HAZARDOUS MATERIALS ABATEMENT SUBTOTAL \$ 22,557.50

HAZARDOUS MATERIALS CONSULTING COST ESTIMATE

| CONSULTING COST | QUANTITY | UNIT COST | TOTAL COST |
|---|----------|-----------------|-------------|
| TCLP SAMPLE ANALYSIS | 1 | \$80.00 EACH | \$ 80.00 |
| TCLP SAMPLE ANALYSIS REPORT | 1 | \$350.00 EACH | \$ 350.00 |
| ASBESTOS ABATEMENT SPECIFICATIONS | 1 | \$1,500.00 EACH | \$ 1,500.00 |
| LEAD ABATEMENT SPECIFICATIONS | 1 | \$500.00 EACH | \$ 500.00 |
| UNIVERSAL WASTE ABATEMENT SPECIFICATION | 1 | \$350.00 EACH | \$ 350.00 |
| ABATEMENT CONTRACT DRAWINGS | 1 | \$1,000.00 EACH | \$ 1,000.00 |
| ALTERNATIVE WORK PRACTICE DEVELOPMENT | 1 | \$500.00 EACH | \$ 500.00 |
| PREBID CONFERENCE | 1 | \$350.00 EACH | \$ 350.00 |
| PRECONSTRUCTION CONFERENCE | 1 | \$350.00 EACH | \$ 350.00 |
| DAILY MONITORING/CLEARANCES | 4 | \$585.00 DAY | \$ 2,340.00 |
| PCM AIR SAMPLE ANALYSIS | 50 | \$8.00 EACH | \$ 400.00 |
| PROJECT MANAGEMENT | 5 | \$100.00 HOUR | \$ 500.00 |
| SENIOR PROJECT MANAGEMENT | 2 | \$130.00 HOUR | \$ 260.00 |
| ASBESTOS ABATEMENT DOCUMENTATION REPORT | 1 | \$600.00 EACH | \$ 600.00 |
| SUBTOTAL | | | \$ 9,080.00 |
| CONSULTING CONTINGENCY | | | \$ 908.00 |
| CONSULTING TOTAL | | | \$ 9,988.00 |

GRAND TOTAL \$ 32,545.50

*NOTE - This estimate does not include the test remediation of PCB-containing materials

APPENDIX 5

**EAGLE ENVIRONMENTAL INC. LICENSES AND LABORATORY
CERTIFICATES**

CERTIFICATE OF ACHIEVEMENT

This certifies that

Raymond R. Folino

has successfully completed the
**Asbestos Site Inspector Refresher Training
Asbestos Accreditation Under TSCA Title II
40 CFR Part 763**

conducted by

*ATC Group Services LLC
73 William Franks Drive
West Springfield, MA 01089
(413) 781-0070*

Gregory Morach

*Principal Instructor: Gregory Morach
May 17, 2018*

Date of Course

*May 17, 2019
Expiration Date*

Gregory Morach

*Regional Training Manager: Gregory Morach
SLAR-6048*

Certificate Number

*May 17, 2018
Examination Date*

STATE OF CONNECTICUT

DEPARTMENT OF PUBLIC HEALTH

PURSUANT TO THE PROVISIONS OF THE GENERAL STATUTES OF CONNECTICUT

THE INDIVIDUAL NAMED BELOW IS CERTIFIED
BY THIS DEPARTMENT AS A

ASBESTOS CONSULTANT-INSPECTOR

RAYMOND R FOLINO

CERTIFICATE NO.
000137

CURRENT THROUGH
10/31/18

VALIDATION NO.
03-634342

[Signature]
SIGNATURE

Raymond R Folino
COMMISSIONER

STATE OF CONNECTICUT

DEPARTMENT OF PUBLIC HEALTH

PURSUANT TO THE PROVISIONS OF THE GENERAL STATUTES OF CONNECTICUT


THE INDIVIDUAL NAMED BELOW IS LICENSED
BY THIS DEPARTMENT AS A
LEAD CONSULTANT CONTRACTOR

EAGLE ENVIRONMENTAL INC.

LICENSE NO.
001723

CURRENT THROUGH
04/30/19

VALIDATION NO.
03-675765


SIGNATURE


COMMISSIONER

CERTIFICATE OF ACHIEVEMENT

This certifies that

Alexis St. Hilaire

44 Fuller Road, Barkhamsted, CT 06063

has successfully completed the
EPA Model Lead Risk Assessor Initial Training
745.225

conducted by
ATC Group Services, LLC
73 William Franks Drive
West Springfield, MA 01089
(413) 781-0070

Neal B. Freud



Gregory Morsch

Principal Instructor: Neal Freud
September 14-15, 2017

Date of Course

June 2, 2017
Interim Expiration Date

Regional Training Director: Gregory Morsch
EPA-659

Certificate Number

STATE OF CONNECTICUT

DEPARTMENT OF PUBLIC HEALTH

PURSUANT TO THE PROVISIONS OF THE GENERAL STATUTES OF CONNECTICUT

THE INDIVIDUAL NAMED BELOW IS CERTIFIED
BY THIS DEPARTMENT AS A
LEAD INSPECTOR RISK ASSESSOR

ALEXIS M ST HILAIRE

CERTIFICATE NO.
002282

CURRENT THROUGH
12/31/18

VALIDATION NO.
03-677021

Alexis M St. Hilaire
SIGNATURE

Raylene
COMMISSIONER

State of Connecticut, Department of Public Health

Approved Environmental Laboratory

THIS IS TO CERTIFY THAT THE LABORATORY DESCRIBED BELOW HAS BEEN APPROVED BY THE STATE DEPARTMENT OF PUBLIC HEALTH PURSUANT TO APPLICABLE PROVISIONS OF THE PUBLIC HEALTH CODE AND GENERAL STATUTES OF CONNECTICUT, FOR MAKING THE EXAMINATIONS, DETERMINATIONS OR TESTS SPECIFIED BELOW WHICH HAVE BEEN AUTHORIZED IN WRITING BY THAT DEPARTMENT.

SCIENTIFIC ANALYTICAL INSTITUTE, INC.

LOCATED AT 4604 DUNDAS DRIVE IN GREENSBORO, NC 27407
AND REGISTERED IN THE NAME OF NATHANIEL DURHAM
THIS CERTIFICATE IS ISSUED IN THE NAME OF NATHANIEL DURHAM WHO HAS BEEN DESIGNATED
BY THE REGISTERED OWNER/AUTHORIZED AGENT TO BE IN CHARGE OF THE LABORATORY WORK COVERED BY THIS CERTIFICATE OF
APPROVAL AS FOLLOWS:


DRINKING WATER
Examination For:
ASBESTOS

ENVIRONMENTAL HEALTH & HOUSING
LEAD IN PAINT
LEAD (PAINT) IN SOIL
LEAD IN DUST WIPES

BUILDING MATERIALS
Examination For:
ASBESTOS FIBERS - PCM, TEM
ASBESTOS IN BULK - PLM, TEM

SEE COMPUTER PRINT-OUT FOR SPECIFIC TESTS APPROVED

EFFECTIVE RENEWAL DATE JANUARY 1, 2018
THIS CERTIFICATE EXPIRES DECEMBER 31, 2019 AND IS REVOCABLE FOR CAUSE BY THE STATE DEPARTMENT OF PUBLIC HEALTH
DATED AT HARTFORD, CONNECTICUT, THIS 19th DAY OF December, 2017



Registration No.

PH-0336

SUZANNE BLANCALOR, MS, MPH
CHIEF, ENVIRONMENTAL HEALTH SECTION